

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

JUL 28 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

Form C-141  
Revised October 10, 2003

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report



Name of Company: Linn Operating	Contact: Brian Wall	
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739	
Facility Name: CMU North Inj Plant (CMU 178)	Facility Type: Injection Plant	
Surface Owner: State	Mineral Owner:	API No.: (closest well) 3002532549

LOCATION OF RELEASE

Unit Letter D	Section 20	Township 17S	Range 33E	Feet from the 1300	North/South Line North	Feet from the 20	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	---------------------	------------------------	---------------

Latitude: 32.8237368378172 Longitude: -103.693895562117

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 105 bbls	Volume Recovered: 100 bbls
Source of Release: transfer pump	Date and Hour of Occurrence: 07/27/2014	Date and Hour of Discovery: 07/27/2014 0700
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson- BLM / Tomas Oberding- NM OCD	
By Whom? Brian Wall	Date and Hour 07/28/2014 1302	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: At appx 7:00a.m. on July 27th 2014 I pulled up to the N. Inj plant and found water standing inside the firewall. I then started investigating the cause of incident. I then found that the pressure gauge on top of the filter pot had blown the top out of it. Therefore when the transfer pump would run it would spray out water.		
Describe Area Affected and Cleanup Action Taken.* : The water ran in low spots around the tanks. 105bbls released, 100bbls recovered. Directions to site: From Maljamar go South on Hwy 126 6/10 of a mile turn on Hwy 125 (Mescalero Rd) go 2.8 miles to Location rd W-3 go 1.2 miles turn right go 1/8th mile then turn left and go 2/10 mile to Injection plant.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor: 	
Title: Construction Foreman II	Approval Date: 7-28-14	Expiration Date: 10-1-14
E-mail Address: bwall@linenergy.com	Conditions of Approval: Site samples re-run	Attached <input type="checkbox"/> 1RP - 3198
Date: 07/28/2014	Phone: 806-367-0645	

\* Attach Additional Sheets If Necessary

Delimitate & remediate area  
as per NMOC guides.  
Submit final C-141 by  
10-1-14

Ogrid 269324  
HTO 1420 949510  
PTO 1420 94970

JUL 29 2014