

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1420957230

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Vanguard Permian	258350	Contact Mike Jones
Address 5847 San Felipe, Suite 3000, Houston TX 77057		Telephone No. (575)390-4611
Facility Name Candelario 24 #1 SWD Battery		Facility Type Line Release
Surface Owner Mosaic Potash Co.	Mineral Owner	API No. 30-015-26536

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	24	23S	28E	1378	FNL	915	FWL	Eddy

Latitude 32.294403 Longitude -104.046428

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release >50 bbls	Volume Recovered 0 bbls
Source of Release 4 inch poly line	Date and Hour of Occurrence July 8, 2014	Date and Hour of Discovery July 8, 2014, 3:00pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Mike Jones	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
JUL 28 2014		
RECEIVED		
Describe Cause of Problem and Remedial Action Taken.* The cut was found in the 4 inch poly line, which released >50 barrels over 2,251 sq ft of pasture land. The line was repaired.		
Describe Area Affected and Cleanup Action Taken.* A total of 2,251 sq ft of pasture land was affected by the release. The site will be assessed and a Corrective Action Plan will be submitted to NMOCD.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Mike Jones	Approved by Environmental Specialist: 	
Title: Production Foreman	Approval Date: 7/29/14	Expiration Date: NA
E-mail Address: mjones@vnrllc.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 8/29/14	Attached <input type="checkbox"/>
Date: _____ Phone: (575)390-4611		

* Attach Additional Sheets If Necessary

RP2-2400

Patterson, Heather, EMNRD

From: Jacob Kamplain <jkamplain@rice-ecs.com>
Sent: Monday, July 28, 2014 8:04 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: hconder@rice-ecs.com; 'Lara Weinheimer'; 'Laura Flores'
Subject: Initial C-141 Vanguard Candelario 24 #1 SWD
Attachments: image0068.pdf

All, attached is the initial C-141 for the Vanguard Candelario 24 #1 SWD. Please feel free to contact me with any questions or concerns. Thank you.



Jacob Kamplain
Project Leader
419 W. Cain
Hobbs, NM 88240
575-942-8221