

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

HOBBS OCD

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG 1 2014

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action **RECEIVED**

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name:	Lusk Deep Unit A #23H	Facility Type:	Battery

Surface Owner: Federal	Mineral Owner:	Lease No. (API#) 30-025-40260
------------------------	----------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	19	T19S	R32E	330	South	380	East	Lea

Latitude Longitude

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release PW 100 bbls	Volume Recovered PW 100 bbls
Source of Release Fire caused by lightning strike	Date and Hour of Occurrence 7/21/2014 8:00 pm	Date and Hour of Discovery 7/21/2014 8:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding - NMOCD / Jeffery Robertson - BLM	
By Whom? Amanda Trujillo	Date and Hour 7/22/2014 3:24 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Lightning struck a water tank and caught fire. The fire department was called to put the fire out.

Describe Area Affected and Cleanup Action Taken.*

The battery area was the only area impacted by the fire. This was a lined facility. All standing fluid was removed from the containment and disposed of at an NMOCD approved facility. The equipment and piping was scrapped and liner removed. The integrity of the liner was examined and found to be intact. A new lined facility will be constructed in the place of the old facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by District Supervisor: 	
Title: Senior Environmental Coordinator	Approval Date: 8-1-14	Expiration Date: _____
E-mail Address: atrujillo@concho.com	Conditions of Approval: _____	Attached <input type="checkbox"/>
Date July 31, 2014 Phone: 575-746-2010	IRP-3203	

* Attach Additional Sheets If Necessary

AUG 01 2014

0911d 229137
170 1421 336966
170 1421 337143