

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

AUG 8 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141  
Revised August 8, 2011

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	State CL #4 CTB	Facility Type	Gathering

Surface Owner	Mineral Owner	API No.30-025-01576(nearest well)
---------------	---------------	-----------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	2	18S	33E					Lea County, NM

Latitude N 32.78270° Longitude W 103.63578°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	3 bbls oil and 4 bbls produced water	Volume Recovered	0 bbls
Source of Release	Frozen valves on a heater treater	Date and Hour of Occurrence	01/24/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking- NMOCD		
By Whom?	Kathy Purvis	Date and Hour	01/23/14 @ 9:55 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Frozen valves on a heater treater caused 3 bbls of oil and 4 bbls of produced water to leak onto the ground. No fluids were recovered and the valves were repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 10' x 10' on location with about 20 feet of overspray off of location. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Chancey Summers	Approved by Environmental Specialist:		
Title: HES Specialist	Approval Date: 8-8-14	Expiration Date: 10-10-14	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 1-30-14 Phone: (575) 397-8216	Site sample required.		1RP-3221

\* Attach Additional Sheets If Necessary

Delinate 8 remediate area  
w/ per NMOCD guides.  
Submit final C-141 by 10-10-14

0911d 16696

1701422 038706

P 101422 038852

AUG 08 2014