


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NA81422635536

Name of Company: Lime Rock Resources II-A, LP <i>277558</i>		Contact: Steven Hunter	
Address: P.O. Box 2147, Roswell, NM 88202		Telephone No.: 713-292-9516	
Facility Name: Eagle 35 L Federal 23		Facility Type: Producing oil well	
Surface Owner: Federal		Mineral Owner State	
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	35	17S	27E	1860'	South	990'	West	Eddy

Latitude *32.78848299* Longitude *-104.25472855*

NATURE OF RELEASE

Type of Release: Hydrochloric Acid	Volume of Release: 40 BBLs	Volume Recovered: 5 BBLs
Source of Release: frac tank leak	Date and Hour of Occurrence 08/13/2014 5:55 am	Date and Hour of Discovery 08/13/2014 5:55 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD/Mike Bratcher, BLM/Solomon Hughes	
By Whom? Talon/LPE David Adkins	Date and Hour 06/13/2014 11:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Lime Rock Resources was completing the well. When personnel arrived on location this morning, a frac tank containing hydrochloric acid was found to be leaking. A vac truck was immediately called to the location and the hydrochloride acid standing on location was recovered. The impacted area was then covered using soda ash.

Describe Area Affected and Cleanup Action Taken.*

The affected area remained on the location and did not impact adjacent pasture lands. Talon/LPE was called to remediate this incident. The impacted area will be scraped approximately 0.25-feet deep and disposed of at a NMOCD approved facility. The excavated area will be subsequently tested for pH. Upon acceptable results, the NMOCD and BLM will be petitioned for approval to backfill and reconstruct the location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Steven J. Hunter

Title: Production Manager

E-mail Address: shunter@limerockresources.com

Date: 08/13/2014

Phone: 713-292-9516

Approved by District Supervisor:

Approval Date: *8/14/14*

Expiration Date: *N/A*

Conditions of Approval:

Remediation per OCD Rule &

Guidelines. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

Attached ☐

* Attach Additional Sheets If Necessary

2RP-2438

Bratcher, Mike, EMNRD

From: David Adkins <dadkins@talonlpe.com>
Sent: Wednesday, August 13, 2014 4:07 PM
To: Bratcher, Mike, EMNRD; Hughes, Solomon
Cc: Patterson, Heather, EMNRD; Amos, James; Steven Hunter
Subject: initial C141
Attachments: Eagle 35 L Federal 23 - Acid Spill - Signed C-141.pdf

All,

Attached please find the initial C-141 for the above referenced location. We will move to remediate this project upon completion of current site activities. Thank you.

Respectfully,

David J. Adkins
District Manager
Talon/LPE
408 West Texas Avenue
Artesia, New Mexico 88210
(575) 746.8768 phone
(575) 746.8905 fax
(575) 441.4835 cell
Email: dadkins@talonlpe.com
Web: www.talonlpe.com



Bratcher, Mike, EMNRD

From: David Adkins <dadkins@talonlpe.com>
Sent: Wednesday, August 13, 2014 11:37 AM
To: Bratcher, Mike, EMNRD; Hughes, Solomon
Cc: Steven J. Hunter
Subject: frac acid release, Lime Rock Eagle 35 L Fed 23

Follow Up Flag: Follow up
Flag Status: Completed

Gentlemen,

This is to notify you that Lime Rock Resources had a release of 40 bbls of hydrochloric acid release from a frac tank this morning at approximately 0550 am. 5 bbls were immediately recovered and soda ash was used to neutralize the impacted area which was contained on the well location. An initial C141 will follow today. Please let me know if you have any questions. Thank you.

Respectfully,

David J. Adkins
District Manager
Talon/LPE
408 West Texas Avenue
Artesia, New Mexico 88210
(575) 746.8768 phone
(575) 746.8905 fax
(575) 441.4835 cell
Email: dadkins@talonlpe.com
Web: www.talonlpe.com

