

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS CO2D

AUG 13 2014

RECEIVED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Mesa Verde 15 Federal #001	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-025-36836

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	15	21S	32E					Lea

Latitude 32.48337 Longitude 103.65727

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	7bbls of oil 10bbls of produced water	Volume Recovered	6.5bbls of oil 10bbls of produced water
Source of Release	Heater treater	Date and Hour of Occurrence	11-26-2013	Date and Hour of Discovery	11-26-2013 06:30am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A one and a half inch split developed in the sleeve of the main body of the heater treater. Replaced heater treater.

Describe Area Affected and Cleanup Action Taken.*

Initially 7bbls of oil and 10bbls of produced water were released from a one and a half split that developed in the heater treater. We were able to recover 6.5bbls of oil and 10bbls of produced water with a vacuum truck. The release was contained in the berm. All free fluids have been recovered. The impacted area will be sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Robert Grubbs Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by District Supervisor: <i>Ernesto J. Spaulde</i>	
Title:	Senior Environmental Coordinator	Approval Date:	8-13-14
E-mail Address:	rgrubbs@concho.com	Expiration Date:	10-15-14
Date:	12-11-2013	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432-661-6601	<i>Site Supervisor require</i>	<i>LRP-3236</i>

* Attach Additional Sheets If Necessary

*Delineate & remediate area
as per NMOCD guidelines
submit final C-141 by 10-15-14*

*09140 229137
N701422 628009
P701422 628209*

AUG 14 2014