

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

HOBBS OCD

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG 13 2014

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

X Initial Report | Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	LPC 31 Federal #001	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-025-37440

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	31	18S	32E					Lea

Latitude 32.70587 Longitude 103.80451

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	20bbls of oil 50bbls of produced water	Volume Recovered	0bbls of oil 16bbls of produced water
Source of Release	Heater treater	Date and Hour of Occurrence	11-18-2013	Date and Hour of Discovery	11-18-2013 02:00a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey R. Leking - NMOCD / James Amos - BLM		
By Whom?	Michelle Mullins	Date and Hour	11-18-2013 11:14 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Gasket failed causing leak to hit the flame arrestor and caught the heater on fire. Replaced the heater treater with other equipment.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 20bbls of Oil and 50bbls of produced water were released from a gasket on a heater treater that failed. We were able to recover 0bbls of Oil and 18bbls of produced water with a vacuum truck. The release was contained inside the tank battery and the location. All free fluid has been recovered. Tetra Tech will sample the spill and will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature:		Approved by District Supervisor:	
Printed Name:	Robert Grubbs Jr.		
Title:	Senior Environmental Coordinator	Approval Date:	8-14-14
E-mail Address:	rgrubbs@concho.com	Expiration Date:	10-16-14
Date:	11-27-2013	Phone:	432-661-6601
		Conditions of Approval:	Attached <input type="checkbox"/>
		Site Sign Approval Releases & remediation area upon NMOCD guide Submit final C-141 by 10-16-2014	IRP-3241 Og rid 229137 NTO 1122 632639 PTO 1422 632796

* Attach Additional Sheets If Necessary

AUG 14 2014