<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II

811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT State of New Mexico
Energy Minerals and Natural Resources

AUG 2 1 2014
Oil Conservation Division

1220 South St. Francis Dr.

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141 Revised August 8, 2011

Santa Fe, NM 87505

			Rele	ease Notific	ation	and Co	rrective A	ction					
7 HMP14	123354	12/03			OPERA?	ΓOR		al Report	П	Final Report			
Name of Co			Contact T				<b></b>		•				
Address 64	<del></del>		<b>Telephone No.</b> 575-513-0628										
Facility Name Cotton Draw Unit 65 SWD						Facility Type Salt Water Disposal							
Surface Owner Federal Mineral Owner						State API No. 30-015-10843							
Surrace Ov	· · · · · · · · · · · · · · · · · · ·						EAGE		1	. 00 010			
TT-'- T	I C	Tourshin	D	Feet from the		NOF RE	Feet from the	East/W	/est Line	County			
Unit Letter Section Township Range Feet from the Nort						N 1980 E Eddy							
			Latitud	e: 32.161085918			ngitude: -103.7	460394	42				
				NAT	URE	OF REL							
Type of Release Spill produced water							Volume of Release 30BBLS Volume Recovered 10BBL  Date and Hour of Occurrence Date and Hour of Discovered						
Source of Release produced water line							Hour of Occurre 4:30 PM	Date and Hour of Discovery 8/15/2014 4:30 PM					
Was Immediate Notice Given?						If YES, To Whom? BLM- Jeff Robertson & OCD- Thomas 'Doc' Oberding							
Yes No Not Required						Date and Hour 8/18/2014 @ noon							
By Whom? Joah Weidemann, Assistant Production Foreman Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse						
☐ Yes ⊠ No						N/A							
If a Waterco	ourse was In	npacted, Des	scribe Ful	ly.*									
N/A Describe Ca	use of Probl	em and Ren	nedial Ac	tion Taken.*									
				de of Cotton Drav	w Unit 6	5 Salt Wate	r Disposal battei	ry where	the Cotto	n Draw Ur	ıit 86 w	ater ties in.	
				8-14-14 to perfo									
				N 8-15-15 the line	e was iso	nated and a	vacuum truck w	as caneo	i out to re	cover the sp	mea w	vater. The	
corroded sec	tion of pipe	nas been re	piaceu.										
Describe Ar													
				d water spilled. A									
				approximately 2 ne the specific clo				imately	20' wide a	it the great	est area	a. I alon	
							J·						
I hereby certi	ify that the ir	nformation g	iven ahove	e is true and comp	lete to th	ne best of my	knowledge and i	ınderstan	d that pur	suant to NM	OCD m	ules and	
regulations a	ll operators a	are required t	o report a	nd/or file certain r	elease no	otifications a	nd perform correc	ctive acti	ons for rel	eases which	may er	ndanger	
				ce of a C-141 repo									
				investigate and reptance of a C-141									
federal, state,				nance of a C-141	report de	des not renev	e the operator of	responsi	officy for C	omphance v	vitii aiiy	y other	
	7 -	- Y					OIL CON	SERV	ATION	DIVISIO	<u>N</u> C		
Signature: Sandra Farley						all kans							
Printed Name: Sandra Farley						Approved by Environmental Specialist:							
						Approval Date: 8 2114 Expiration Date: NA							
E-mail Addre	ess: Sandy.F	arley@dvn.	com		,	Conditions o	f Approval: ation per OCE	ع الماء الا	۶,	Attached	i 🗆		
Date: 8/18/1	4	Ph	one: <b>575.</b>	746.5587			. SUBMIT REM						
Attach Addi				4			FALMOLATER			•		DONAKO	
						ų.	121114				1	-N-DATA	