

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form
HOBBS OCD
AUG 28 2014

Release Notification and Corrective Action RECEIVED

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Road; Hobbs, NM 88240	Telephone No.	575-397-8216
Facility Name	WA Ramsey NCT D Battery	Facility Type	Gathering

Surface Owner	Mineral Owner	Lease No:
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	28	24S	38E					Lea County, NM

Latitude N 32.18678°

Longitude W 103.07159°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	200 bbls of oil & water mix	Volume Recovered	150 bbls
Source of Release	Flow line rupture	Date and Hour of Occurrence	01/16/2012 @ 2:30 p.m.	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Chancey Summers	Geoffrey Leking			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	Date and Hour 02/16/2012 @ 11:40 a.m.			
		If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A line rupture caused 200 bbls of water to leak onto the ground. A vacuum truck was able to recover 150 bbls and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

A line rupture caused 200 bbls of water to leak onto the ground. A vacuum truck was able to recover 150 bbls and the line was repaired or replaced. Remediation was completed in accordance with the remediation plan approved by Geoffrey Leking of NMOCD via email on 03/02/2012.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				OIL CONSERVATION DIVISION	
Printed Name:	Chancey Summers			Approved by District Supervisor: 	
Title:	HES Advisor			Approval Date:	8-28-14
E-mail Address:	chancey_summers@oxy.com			Expiration Date:	—
Date:	8-21-14			Conditions of Approval:	—
Phone:				Attached <input type="checkbox"/>	1RP 3279

* Attach Additional Sheets If Necessary

AUG 28 2014

ETO 1424 02967
NTO 1424 030058
PTO 1424 030270