HOBBS OCD

District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 AUG 8 2014 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance RECEIVED with Rule 116 on back side of form

Release Notification and Corrective Action

·	. <u></u>	OPERATOR	🛛 Initial Report	Final Report
Name of Company Iless Corporation		Contact Rick Gillespie, Senior	EHS Specialist	
Address 100 NW 7th Street; Seminole, TX 79360		Telephone No. (432) 758-6713		
Facility Name Texaco State E Battery	#79	Facility Type Battery		
Surface Owner	Mineral Owner		Lease No.	

Surface Owner			Mineral (Iwner		Lease M	No.	
LOCATION OF RELEASE								
I Twit I attor San	ting Township	Dence Fe	sat fram that	Marth Bauth Line	East Grama alas	Carton Land Line	County	_

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County	
	1	205	36E					Lea County, NM	

Latitude <u>N 32.59872</u> Longitu

Longitude <u>W 103.31210</u>

NATURE OF RELEASE

Type of Release Unknown, historical	Volume of Release Unknown, historical	Volume Recovered Unknown, historical					
Source of Release Unknown, historical	Date and Hour of Occurrence	Date and Hour of Discovery					
	Unknown	Unknown					
Was Immediate Notice Given?	If YES, To Whom?	-					
Ycs 🗌 No 🛛 Not Required	n/a						
By Whom? n/a	Date and Hour n/a						
Was a Watercourse Reached?	If YES, Volume Impacting the Wat	PTTOUTS?					
Yes X No	n/a						
If a Watercourse was Impacted, Describe Fully.*							
n/a							
Describe Cause of Problem and Remedial Action Taken.*							
This is a former tank battery that has been abandoned. The hydrocarbon	impact is historical in nature. Hess ha	s a generic remediation plan approved by					
the NMOCD.							
Describe Area Affected and Cleanup Action Taken.*							
The tank battery site will be assessed and delineated. Samples will be co	lected and the results will be discusse	d with the NMOCD to create a remediation					
and closure plan.							
Y Long to say if G. A. Marine Grant in since share in the set of some late to d							
I hereby certify that the information given above is true and complete to the regulations all operators are required to report and/or file certain release p							
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability							
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health							
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other							
federal, state, or local laws and/or regulations.							
	OIL CONSERV	ATION DIVISION					
Signature: Tach - Jullespic							
Printed Name: Rick Gillespie	Approved by District Supervisor.	My .					
Title: Senior EHS Specialist	Approval Date: 9-11-19	Expiration Date: 10-13-19					
E-mail Address: rgillespie@hess.com	Conditions of Approval:						
L-man (Kou coo. Igmoophagnooscom	Submit Ful 6141	Attached					
Date: 6-8-12 Phone: (432) 758-6713		" IRP- 3281					
Attach Additional Sheets If Necessary	10-13-14.	0grid 41421					

Situr solphe report. No 1424 039951 Demote Crestiate and pto1424 040039 9 Sprymo CO Juit Fto 1424 039815

ALIC 2 8 2014