

# NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

SEP 03 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

## Release Notification and Corrective Action

Name of Company <b>Mewbourne Oil Co</b>		Contact <b>Zach Thomas</b>	
Address <b>701 S Cecil, Hobbs, NM</b>		Telephone No. <b>575-602-2188</b>	
Facility Name <b>Waltersheid #1</b>		Facility Type <b>Gas Well</b>	

Surface Owner <b>Private</b>	Mineral Owner <b>Private</b>	API No. <b>30-015-25117</b>
------------------------------	------------------------------	-----------------------------

## LOCATION OF RELEASE

Unit Letter <b>E</b>	Section <b>14</b>	Township <b>22S</b>	Range <b>27E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Eddy</b>
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------

Latitude 32.3940 Longitude -104.1687

## NATURE OF RELEASE

Type of Release <b>Gas</b>	Volume of Release <b>Unknown</b>	Volume Recovered <b>0</b>
Source of Release <b>Hammer Union/Gas Line</b>	Date and Hour of Occurrence <b>Unknown</b>	Date and Hour of Discovery <b>5 Aug 14 A.M.</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>N/A</b>	
By Whom? <b>N/A</b>	Date and Hour <b>N/A</b>	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>Unknown</b>	
If a Watercourse was Impacted, Describe Fully.* <b>N/A</b>		

Describe Cause of Problem and Remedial Action Taken.\*  
**Hammer Union/Line developed a leak at the point where the line makes a 90 degree turn to the east going under Grandi Road. Upon discovery, the line was shut in and the impacted area was excavated to expose the line. Once exposed, the line was repaired and put back in service. The impacted soil that was excavated was transported to a division approved disposal facility. An environmental remediation company will be contracted for a complete remediation of the impacted area. During the remediation/excavation process, groundwater was encountered at approximately 12' BGS on the west side of the road. A groundwater sample was obtained and sent for lab analysis. Results will be presented to NM OCD.**

Describe Area Affected and Cleanup Action Taken.\*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <b>Z. Thomas</b>	OIL CONSERVATION DIVISION	
Printed Name: <b>Zach Thomas</b>	Approved by Environmental Specialist: <b>[Signature]</b>	
Title: <b>HSE</b>	Approval Date: <b>9/3/14</b>	Expiration Date:
E-mail Address: <b>zthomas@mewbourne.com</b>	Conditions of Approval: Remediation per OCD Rule & Guidelines.	
Date: <b>3 Sept 14</b> Phone: <b>575-602-2188</b>	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: **10/3/14**

**2RP-2469**

**Patterson, Heather, EMNRD**

---

**From:** Vernon Black <VBlack@Hungry-Horse.com>  
**Sent:** Wednesday, September 03, 2014 10:00 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Subject:** Emailing: C141- Waltersheid #1 (8-5-14) Initial.pdf  
**Attachments:** C141- Waltersheid #1 (8-5-14) Initial.pdf

Mike/Heather,

Sorry about getting this to you so late, but I just realized that I did not send it when we starte4d the work. Please give me a call if you have any questions. I'll get with you as soon as I get the lab results back on the groundwater sample.

Vernon K. Black  
Hungry Horse, LLC  
PO Box 1058  
Hobbs, NM 88241  
575-393-3386 office  
575-631-2253 cell