

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240District II
811 S. First St., Artesia, NM 88210District III
1000 Rio Brazos Road, Aztec, NM 87410District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

SEP 02 2014

RECEIVED

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Form C-141
Revised August 8, 2011Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Murchison Oil & Gas, Inc.	Contact	Greg Boans
Address	1100 Mira Vista Blvd, Plano, TX 75093	Telephone No.	(575) 628-3932
Facility Name	Jackson Unit #19H	Facility Type	Production Facility
Surface Owner	State of New Mexico	Mineral Owner	API No. 30-025-41138

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	21	24S	33E	200	South	940	East	Lea

Latitude 32° 11' 47.154" N Longitude 103° 34' 49.364" W

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	50 bbls	Volume Recovered	16 bbls
Source of Release	Transport truck	Date and Hour of Occurrence	8/15/2014 1:00 am	Date and Hour of Discovery	8/15/2014 3:30 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Email to Tomas Oberding			
By Whom?	Randy Hicks	Date and Hour	8/15/2014 1:24 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

n/a

Describe Cause of Problem and Remedial Action Taken.*

While loading from the battery, a driver fell asleep causing an overflow from his truck, losing approximately 50 barrels of crude oil onto the facility pad. At 3:30 am the trucking company notified Murchison of the release and approximately 16 barrels were recovered, resulting in a net release of approximately 34 barrels.

Describe Area Affected and Cleanup Action Taken.*

The impacted material was immediately removed to a plastic liner placed on site and clean caliche was used to replace the pad material. The oily material was removed to a permitted disposal facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name:

Greg Boans

Approved by Environmental Specialist:

Title:

Production Superintendent

Approval Date: 9-2-14

Expiration Date: 11-1-14

E-mail Address:

gboans@jdmii.com

Conditions of Approval:

Site Sample report

Attached ☐

Date: 8/29/2014

Phone:

(575) 628-3932

IRP-3288

* Attach Additional Sheets If Necessary

Return to E-mail address
per NMOCD guide. Submit final
C-141 by 11-1-14

Ogrod-15363
1701424526180
1701424521323

SEP 05 2014