

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

SEP 03 2014

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Apache Corporation	Contact	Natalie Gladden
Address	PO Box 1849 Eunice, NM 88231	Telephone No.	575-390-4186
Facility Name	White Owl Battery (nearest well #1)	Facility Type	Production Facility
Surface Owner	Unknown	Mineral Owner	ST of NM
		API No.	30-025-36689

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	2	20S	38E	582	FNL	330	FWL	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Oil/Water	Volume of Release	12	Volume Recovered	10
Source of Release	Fire tube	Date and Hour of Occurrence	12/06/11	Date and Hour of Discovery	12/06/11
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Natalie Gladden	Date and Hour 12/7 1150am			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*



Southern Union's gas compressor went down overnight and the heater treater pressured up resulting in a failure of the fire tube gasket. Spray area was backdragged immediately. Most of the fluid remained inside the bermed area, but did spray the pasture area.

Describe Area Affected and Cleanup Action Taken.\*

Clean up will follow the NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Natalie Gladden	Approval Date: 9-3-14	Expiration Date: 11-3-14
Title: EHS Environmental Tech	Conditions of Approval: Site specific report	
E-mail Address: natalie.gladden@apachecorp.com	Attached <input type="checkbox"/>	
Date: 12/12/11 Phone: 575-390-4186	IRP 3306	

\* Attach Additional Sheets If Necessary

Delisted & remediated area  
as per NMOCD guidelines  
submit final C-141 by  
11-3-14

Ogild 873  
N70 1424654460  
P70 1424654600