

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
100 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR		<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	MC State #001	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	API No. 30-015-25118

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	23	17S	28E					Eddy

Latitude N 32.81976° Longitude W 104.14595°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	8 bbls	Volume Recovered	2 bbls
Source of Release	Main produced water line	Date and Hour of Occurrence	11/09/2013	Date and Hour of Discovery	11/09/2013 @ 07:00 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

... a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 45 connection from the water pump failed. Replaced the 45 connection to prevent reoccurrence.

Describe Area Affected and Cleanup Action Taken.*

Initially an estimated 8 bbls were released due to a faulty 45 connection from the water pump. We were able to recover 2 bbls with a vacuum truck. All free fluids have been recovered. The spill was located inside the facility walls and the adjacent pasture. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator		Approval Date: 8/25/14	Expiration Date: <i>NA</i>
mail Address: rgrubbs@concho.com		Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: 4-22-14 Phone: (432) 661-6601			

* Attach Additional Sheets If Necessary

2RP-2068

