

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OGD

Form C-141
Revised August 8, 2011

AUG 28 2014
Submit Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Eagle Feather Federal #2	Facility Type: Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-025-38885
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 21	Township 26S	Range 36E	Feet from the 660'	North/South Line North	Feet from the 1630'	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	---------------

Latitude N32 6'23" Longitude W103 11'37"

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 20 bbls	Volume Recovered: 19 bbls
Source of Release: Circulating pump	Date and Hour of Occurrence: 8-26-2014 7:00 am	Date and Hour of Discovery: 8-26-2014 7:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A valve on a circulating pump was left open causing the release. A vacuum truck was dispatched to remove all standing fluids and gravel was removed.

Describe Area Affected and Cleanup Action Taken.*

The impacted area was 20' x 30' and contained within the bermed area. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Amanda Trujillo

Title: Senior Environmental Coordinator

E-mail Address: atrujillo@concho.com

Date: August 29, 2014

Phone: 575-748-6940

Approved by Environmental Specialist:

Approval Date: 8-29-14

Expiration Date: 10-29-14

Conditions of Approval:

Site Specific Remedial
Action & remediate area
in per NMOCD guidelines.
Submit final C-141 by
10-29-14

Attached ☐

IRP-3287

OGD 229137

NTO 1424 157009

Pto 1424 157118

* Attach Additional Sheets If Necessary

SEP 05 2014

SEP 08 2014