District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ayenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective ActionNM OIL CONSERVATION

ARTESIA DISTRICT

SEP 1 1 2014

							RECEIVED						
NABIY	2553	32950)			OPERA:	TOR	X	Initi	al Report	☐ Fir	nal Repor	
Name of Co	əmpan <u>y; C</u>	layton Willi	ams	25706			uis Gonzales						
		ve Suite 110	Telephone No: 432-661-4708										
Facility Na	me: State	20 B Battery	•			Facility Typ	e: Battery	***************************************					
Surface Owner: State Mineral Owner:							Lease No. 3001530918						
				LOCA	ATIO	N OF RE	LEASE						
Unit Letter A	Section 20				North/	forth/South Line Feet from the			West Line County: Eddy County				
			La	titude <u>32.8269</u>	73	Longitud	e <u>-104.088396</u>						
				NAT	URE	OF REL	EASE						
Type of Release: Produced Water/Oil							Release: 55		Volume Recovered: 45				
Source of Re		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	Date/Hour of Occurrence:9/9/14 Date/				lour of Discovery:9/9/14						
Was Immedi	ate Notice (Yes [] No 🔲 Not Re	equired	Mike Brate							
By Whom? Eric Garcia							- Date and Hour: 9/10/2014						
Was a Water	emirsé Read	ched?	If YES. Volume Impacting the Watercourse: N/A										
di a-Watercoi	ırse was Im	pacted. Descr	be Fully.*			l .					······································		
NA													
9.9.2014		em and Remed					· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·				
standing fluid	d. Recovere	ed approx 45	barrels.	line from the batt Hauled the fluid to all was performed	o the dis	e Jenna Com posal. Finall	SWD. The line vy. a crew installed	was repaired d a barb wire	l. Also e fence	vacuum fro around the	ick remove spill site. T	d the lictures of	
Describe Are	a Affected a	and Cleanup A	ction Tak	en.*									
The area affe	eted was pa sa backhoe	sture. The ard	ea measure to begin th	es appróx., 2000 s ne delineation pro-	q.ft. On	ië call was pe	rformed on 9/10/	2014 by Rep	oublic I	Backhoe Scr	vice LLC.	Once the	
will be haule guideline for	d off and di	sposed at R36	0. Then e	lean soil will be h	auled in	to back fill t	he area. The rem	ediation pro	cess wi	Il adhere to	the NMOC	D.	
I hereby certi	ly that the i	nformation giv	ven above	is true and compl	ete to the	e best of my l	enowledge and un	nderstand the	nt pursu	ant to NMC	OCD rules a	ınd	
regulations al	Loperators	are required to	report an	d/or file certain re	lease no	tifications an	d perform correct	ive actions f	or relea	ises which n	nav endang	er	
should their c	or the circli perations h	omnem. The ave failed to a	acceptane dequately	e of a C-141 report investigate and re	n by inc	contamination	irked as "Final Re on that nose a thre	port" does r	iot retic	eve the opera-	ator of Babi er human l	lity bealth	
or the enviror	iment. In a	ddition, NMO	CD accept	tance of a C-141 r	eport do	es not relieve	the operator of re	esponsibility	ofor co	mpliance w	ith any othe	r	
lederal, state.	ordocal lav	vs and/or regu	lations.				OIL CONG	CEDVAT	MON	DIVICIO			
Printed Name: DAVE DUNLAP						OIL CONSERVATION DIVISION							
						Approved by Dist Signature Bisor Alle Desarrate							
	1			/ .		*	A)		<i></i>	TOWER !			
Title: /	rod.	Foren	MAN	***************************************		Approval Dat			ration I	Qate: N	<u>H</u>		
1,-mail Addre	s dd	UNIAP (DelAy	How William	es Cas	∴Condition Remediat	ns of Approval: tion per OCD Ru	: ule & Guid	elines	- Attached			
Date: 9-		, .	Phone:	575-390	2000	, SUBMIT I	REMEDIATION	PROPOSA	L NO	Amacied	10 A #	07	
· · · · · · · · · · · · · · · · · · ·						LATER TH	IAN: <i>U</i>]_	<u> 1114</u>		- 7.1	11-124	カソー	

Bratcher, Mike, EMNRD

From:

eric garcia <ericgarcia62@hotmail.com>

Sent:

Thursday, September 11, 2014 12:37 PM

To:

Igonzalez@claytonwilliams.com; Bratcher, Mike, EMNRD; eric garcia

Subject:

C-141 Form State 20 B Battery

Attachments:

C141 State 20 B Battery.pdf

Mr. Bratcher,

On 09/10/2014, I called you to give verbal notification of the spill by the State 20 B Battery operated by Clayton Williams. The following attachment contains the C-141 form. IF you have any questions please call me at (575) 631-0131 or Luis Gonzalez at (432) 661-4708.

Thank You

Eric Garcia

Republic Backhoe Service LLC.

Bustamante, Amalia, EMNRD

From:

Bratcher, Mike, EMNRD

Sent:

Thursday, September 11, 2014 3:42 PM

To:

Bustamante, Amalia, EMNRD

Subject:

FW: C-141 Form State 20 B Battery

Amalia,

Since we can't enter ½ bbls, just call it 2 bbls oil released w/1 bbl recovered. Thanks – Mike

From: Gonzalez, Luis [mailto:LGonzalez@claytonwilliams.com]

Sent: Thursday, September 11, 2014 3:14 PM

To: Bratcher, Mike, EMNRD

Subject: RE: C-141 Form State 20 B Battery

Hi Mike! I finally reached our field foreman and asked him about the amount of oil loss, he stated that it was a very thin layer of oil, He figured that it was anywhere from 1 to 2 Bbls Max. I would call it 2bbls oil loss and recovered. I would think a barrel and a half.



Clayton Williams Energy Inc.

Luis Gonzalez
Environmental Regulatory Manager
Igonzalez@claytonwilliams.com
(432)683-3298 Office
(432)661-4708 Cell

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]

Sent: Thursday, September 11, 2014 3:53 PM

To: eric garcia; Gonzalez, Luis

Cc: Patterson, Heather, EMNRD; Bustamante, Amalia, EMNRD

Subject: RE: C-141 Form State 20 B Battery

Louis,

This C-141 lists 55 bbls PW & Oil released with 45 bbls recovered. Can you give us an idea on how much of the fluid was oil and how much was PW? We need it broken out for data entry.

Thanks in advance,

Mike Bratcher NMOCD District 2 811 S. First Street Artesia, NM 88210 O: 575-748-1283 X108 C: 575-626-0857