

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

Form C-141
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

SEP 15 2014

Release Notification and Corrective Action

RECEIVED

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	Contact: Bob Akin	
Address: 2130 W Bender Hobbs, NM 88260	Telephone No.: 575-738-1739	
Facility Name: Barclay State Battery - Barclay State #2	Facility Type: Battery	
Surface Owner: State	Mineral Owner: State	API No.: 3001529590

LOCATION OF RELEASE

Unit Letter J	Section 02	Township 23S	Range 31E	Feet from the 1980	North/South Line South	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.33163 Longitude: -103.74577

NATURE OF RELEASE

Type of Release: Oil / Produced Water	Volume of Release: 15 bbls / 400 bbls	Volume Recovered: 10 bbls / 385 bbls
Source of Release: Pump	Date and Hour of Occurrence: 10/05/2012 7:30am	Date and Hour of Discovery: 10/05/2012 8am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy Dade- NM OCD	
By Whom? Bob Akin	Date and Hour 10/05/2012 2:19pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: RECEIVED PHONE CALL THAT TANKS WERE OVER FLOWING. ARRIVED TO LOCATION AND H-PUMP WAS DOWN ON DIGITAL OVERLOAD.

Describe Area Affected and Cleanup Action Taken.* : CALLED FOR A VAC TRUCK AND ELECTRICIAN.ALL FLUID CONTAINED IN FIREWALL. Further remedial action pending.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Bob Akin*

Printed Name: Bob Akin

Title: Production Forman

E-mail Address: rakin@linenergy.com

Date: 10/08/2012

Phone: 575-390-8007

Approved by District Supervisor:

Ernesto Spruiell

Approval Date: 9-15-14

Expiration Date: 11-15-14

Conditions of Approval:

Site Supervisor

Attached ☐

IRP-3719

* Attach Additional Sheets If Necessary

SEP 16 2014

Revised & completed as per NMOCD guide. Submit final C-141 by 11-15-14.

*ogrid 269324
n701425 853089
p701425 853252*