

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	U.S 13 Federal #2	Facility Type	Production

Surface Owner	BLM	Mineral Owner		API No.	
---------------	-----	---------------	--	---------	--

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	13	22S	24E	840	South	1650	East	Eddy County, NM

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	15 bbls	Volume Recovered	0 bbls
Source of Release	Flow line leak	Date and Hour of Occurrence	08/19/2011	Date and Hour of Discovery	

Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?
-----------------------------	---	------------------

By Whom?	Date and Hour
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

RECEIVED



JAN 23 2014

NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.\*  
Corrosion on a flow line caused it to blow out and leak 15 bbls of produced water onto the ground. No free liquids could be recovered and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area is located inside the lined battery with very little overspray in the surrounding pasture. Remediation was completed in accordance with a plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Christopher Jones	Approved by District Supervisor:	
Title:	HES Specialist	Approval Date:	6/30/14
E-mail Address:	Christopher_Jones@oxy.com	Expiration Date:	NA
Date:	1/16/14	Conditions of Approval:	Final
Phone:	(575) 628-4121	Attached	<input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2 RP - 885