

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OGD

Form C-141
Revised October 10, 2003

SEP 25 2010 Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report



Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Mescalero ARL State #1	API Number 30-025-33969	Facility Type Battery
Surface Owner State	Mineral Owner State	Lease No. VA-0621

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	2	10S	32E	330	South	330	East	Lea

Latitude 33.46878 Longitude 103.63456

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 15 B/O	Volume Recovered 15 B/O
Source of Release Water Leg	Date and Hour of Occurrence 12/12/2010 PM	Date and Hour of Discovery 12/12/2010 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Water leg became plugged and tank ran over, vacuum truck and roustabout crew called to location.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 12'. All inside berm, the battery is lined with a 20 mil liner. Water leg unplugged, vacuum truck picked up all oil; impacted gravel was removed and taken to an NMOCD approved facility. New, clean gravel to be brought in to replace impacted gravel. Depth to Ground Water: 50-99' (approx. 65', per ChevronTexaco trend map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on battery being lined, all released oil recovered and impacted gravel taken to an NMOCD approved facility and replaced with new, clean gravel, Yates Petroleum Corporation requests closure.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor: 	
Title: Environmental Regulatory Agent	Approval Date: 9-25-14	Expiration Date: _____
E-mail Address: boba@ypcnm.com	Conditions of Approval: _____	Attached <input type="checkbox"/>
Date: Thursday, December 16, 2010	Phone: 575-748-4217	1RP-3358

* Attach Additional Sheets If Necessary

MAILED

SEP 25 2014

170 1426 829295
P 70 1426 829461