

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

OCT 06 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1428154809 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Devon Energy	Contact Rudy Zuniga (Production Foreman)
Address PO Box 250 Artesia, NM 88211	Telephone No. (575) 390-5435
Facility Name Vega 29 Federal Com 1H Battery (closest well - Vega 29 Fed Com 3H)	Facility Type Oil and Gas Production

Surface Owner BLM	Mineral Owner BLM	API No. 30-015-41624 (3H)
--------------------------	--------------------------	----------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	29	19S	31E	147'	North Line	2470'	East Line	Eddy County

Latitude 32.63837 Longitude -103.89069

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 35	Volume Recovered 20
Source of Release Failure to haul fluid (Arapahoe)	Date and Hour of Occurrence 10/04/2014 11am	Date and Hour of Discovery 10/04/2014 11am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Natalie Gladden (DFSI Environmental)	Date and Hour 10/06/2014 10am - BLM J. Robertson/10:02am NMOCD M. Bratcher	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Arapahoe Trucking failed to haul fluid causing the tanks to overflow. A vacuum truck was called out to recover standing fluid and was able to recover approximately 20bbls of produced water. DFSI completed the Environmental Assessment, mapped the site and surface samples.

Describe Area Affected and Cleanup Action Taken.*

A total of 13,656 sq. ft. of impacted surface was determined. Twelve sample points were set, sampled and will be delineated. Once the site has been fully delineated a Remediation Work Plan will be submitted to both the BLM/NMOCD. All rules and regulations will be followed to closure of this site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Stacie Singleton</u>	OIL CONSERVATION DIVISION	
Printed Name: Stacie Singleton	Approved by Environmental Specialist: <u>Mike Bratcher</u>	
Title: Environmental Professional	Approval Date: <u>10/8/14</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>Stacie.singleton@dvn.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/06/2014 Phone: (575) 513-2129	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 11/8/14

2RP-2533

Bratcher, Mike, EMNRD

From: Singleton, Stacie <Stacie.Singleton@dvn.com>
Sent: Monday, October 06, 2014 3:54 PM
To: Bratcher, Mike, EMNRD; jlrobertson@blm.gov
Cc: Frazier, Billy; Biagi, Chris; Zuniga, Rudy; Natalie Gladden
Subject: C141 for Vega 29 Fed Com 1H Battery
Attachments: 141006_Vega29FedCom1H_C141.pdf

Mike and Jeffery,

Attached, please find the C141 for Saturday's produced water spill at Vega 29 Fed Com 1H Battery.

Thank you,
Stacie

Stacie Singleton
Environmental Professional

Devon Energy Corporation
6488 Seven Rivers Highway
Artesia, New Mexico 88210
(575) 748-1844 Direct
(575) 513-2129 Mobile
stacie.singleton@dvn.com



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

2RP-2533