

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

OCT 09 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Regency Field Services LLC.	Contact: Crystal Callaway
Address: 301 Commerce Street, Suite 700, Fort Worth, TX 76102	Telephone No.: (817) 302-9407
Facility Name: L5 to MF	Facility Type: Natural Gas Gathering
Surface Owner: Millard Deck	Mineral Owner: State
API No.: 30025-39231-00-00	

LOCATION OF RELEASE

Unit Letter O	Section 15	Township 21S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea.
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.472081 Longitude -103.151236

NATURE OF RELEASE

Type of Release: Crude Oil and Natural Gas	Volume of Release: Greater than 50 MCF gas, Greater than 5 bbls crude oil	Volume Recovered: None
Source of Release: 10" Natural Gas Pipeline	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 01/07/2009 9:07 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Tony Savoie	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The 10" Natural gas pipeline developed a leak prior to the discovery date of 02/26/2009. The leak area had been excavated and three (3) temporary leak clamps had been installed on the pipeline. There were no fluids standing or gas leaking upon discovery. There were two (2) area noted during the discovery that were oil stained. One (1) area measured approximately 10' x 18' and the other measured approximately 40' x 20'.

Describe Area Affected and Cleanup Action Taken.*

Reportedly, in 2009, approximately 2,904 cubic yards (yd³) of impacted soil was excavate from the release site by Basin Environmental and transported to an approved Landfarm. Further excavation was determined to be unsafe and impracticable given the risks associated with the depth of the excavation and the proximity of the floor of the excavation to groundwater. Two (2) confirmation samples exceeded the NMOCD Guidelines and as a result one (1) monitor well was installed in order to confirm there was not an impact to groundwater. Five (5) sampling events confirmed that there was not a chloride impact and laboratory results indicated that BTEX concentrations were less than the laboratory MDL for each of the submitted groundwater samples, with the exception of benzene at 0.0258 mg/L for the January 9, 2014 sampling event.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <u>Crystal Callaway</u>	Approved by Environmental Specialist:	
Printed Name: <u>Crystal Callaway</u>		
Title: <u>Sr. Environmental Remediation Spec</u>	Approval Date: <u>10-9-14</u>	Expiration Date: <u> </u>
E-mail Address: <u>CRYSTAL.CALLAWAY@RegencyNS.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>10/3/14</u>	Phone: <u>817-302-1514</u>	<u>IRP-2185</u>

* Attach Additional Sheets If Necessary