

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

# NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

OCT 10 2014

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

NAB1428733041

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	RKI E&P, LLC	Contact	Zack Laird
Address	210 Park Ave. - Ste. 900, OKC, OK 73102	Telephone No.	405-742-2696
Facility Name	Federal G Gas Com #1	Facility Type	Oil and Gas Well

Surface Owner	Federal	Mineral Owner	Federal	API No.	30-015-20848
---------------	---------	---------------	---------	---------	--------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	21	20S	30E		1650 FSL		1900FEL	Eddy

Latitude 32.5561146081723 Longitude -103.974812991781

### NATURE OF RELEASE

Type of Release	Oil and Produced Water	Volume of Release	15Bbls	Volume Recovered	14Bbls
Source of Release	Produced Water Tank	Date and Hour of Occurrence	10/09/14 - Unknown	Date and Hour of Discovery	10/09/14 - 0900hrs
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\* N/A.

Describe Cause of Problem and Remedial Action Taken.\*

Produced Water tank developed a hole and allowed PW to leak from tank into secondary containment (earthen). A vacuum truck was used to recover free liquids and empty tank.

Describe Area Affected and Cleanup Action Taken.\*

All fluid remained in earthen tank dike, free fluids were recovered with vacuum truck.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Zack Laird	Approved by Environmental Specialist:		
Title: Sr. EHS Manager	Approval Date: 10/10/14	Expiration Date: NA	
E-mail Address: ZLaird@rkixp.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 10/09/14	Phone: 405-987-2213		

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 11/10/14

\* Attach Additional Sheets If Necessary

2RP-2542

**Patterson, Heather, EMNRD**

---

**From:** Hughes, Solomon <shughes@blm.gov>  
**Sent:** Friday, October 10, 2014 1:28 PM  
**To:** Zackary Laird  
**Cc:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; Oberding, Tomas, EMNRD  
**Subject:** Re: RKI E&P Spill Notification and C-141 Reports  
**Attachments:** NM\_FedGGasCom1\_SignedIC141(100914).pdf; NM\_YatesFed1\_SignedIC141(100914).pdf

Zack,

Message received.

Thanks,  
Sol

**Sol Hughes**  
Environmental Protection Division  
Bureau of Land Management  
620 E. Greene St  
Carlsbad, NM

Office: 575.234.5951  
Cell: 575.499.3378

On Fri, Oct 10, 2014 at 9:18 AM, Zackary Laird <[ZLaird@rkixp.com](mailto:ZLaird@rkixp.com)> wrote:

Sol,

Attached please find completed OCD form C-141s for two recent spills occurring on RKI operated leases in Eddy County, NM.

Please feel free to contact myself or a local RKI representative with any questions.

Kind Regards,

Zack Laird | Sr. EHS Manager

**RKI Exploration & Production, LLC**

LRP- 2542

210 Park Avenue, Suite 900 | Oklahoma City, OK 73102

405.987.2213 (o) | 405.742.2696 (m) | [ZLaird@rkixp.com](mailto:ZLaird@rkixp.com)