

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCT 15 2014

Form C-141
Revised August 8, 2011

RECEIVED by to appropriate District Office in accordance with 19/15.29 NMAC.

Release Notification and Corrective Action

NAB1428950747

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company 14744	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Black Lake 5 PA St. Com #1H	Facility Type: Producing Oil Well

Surface Owner: State	Mineral Owner: State	API No. 30-015-41124
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 5	Township 25S	Range 28E	Feet from the 150'	North/South Line South	Feet from the 330'	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.1523553 Longitude -104.1021419

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: Produced water estimated 430 bbls.	Volume Recovered: PW(420 bbls)
Source of Release: Water Tank	Date and Hour of Occurrence 10-13-14	Date and Hour of Discovery 10-13-14 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson	
By Whom? Zack Thomas	Date and Hour 10-14-14 7:35 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Water transfer pump failed causing water tanks to run over into secondary containment. Secondary containment also ran over putting an estimated 30 bbls on the ground east of tanks out into the pasture. Well was shut-in upon pumper arrival to stop the release. Vacuum trucks recovered all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

Affected areas- Well pad around tank secondary containment on northeast side. Well pad surface in between tanks and well head. Water also ran off location on Northeast side down an estimated 200 yards through the pasture.
Cleanup Action- All contaminated caliche and topsoil will be dug out and hauled off. All produced water that was recovered (420 bbls) was hauled off to a SWD. Final remediation will be conducted in accordance with the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Z. Thomas</u>	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Signed By <u>Mike Brannon</u> Approved by Environmental Specialist	
Title: Environmental Rep.	Approval Date: <u>11/16/14</u>	Expiration Date:
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-14-14	Phone: 575-602-2188	

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 11/16/14

2RP-2555

Bratcher, Mike, EMNRD

From: Zack Thomas <zthomas@mewbourne.com>
Sent: Wednesday, October 15, 2014 9:10 AM
To: Bratcher, Mike, EMNRD
Subject: Black Lake C141
Attachments: C141- Black Lake 5 PA St. Com #1H (10-13-14) initial.pdf



Zack Thomas

Mewbourne Oil Company
PO Box 5270
Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252
(575) 602-2188
Email: zthomas@mewbourne.com

**ENVIRONMENTAL RELEASE NOTIFICATION
Call-In Sheet**

Date: 10/14/14

Zack Thomas from Newbourne
(Person Reporting) (Company)

is reporting a release at the Black Lake 5 PA St Com/H 2nd Release?
(Site)

API# 015-41124, Sec. 5 T 25s - R 28E.

Discovered.

Occurred on: 10/13/14 at Noon AM/PM.
(Date of Occurrence) (Time of Occurrence)

Volume released: Est 430 bbls pw

C-141 received: 10/15/14

Volume recovered: Est 420 bbls

2RP- 2555

Briefly Describe Cause of Problem and action taken: overflowed containment - some
fluid off pad in pasture

()
(Initials)

**FLARE NOTIFICATION
Call-In Sheet**

Date: _____

Report Flare for _____ from _____
(Reporting Company) (Person Reporting)

Occurred on: _____ at _____ AM/PM.
(Date) (Time of Occurrence)

C-129/C-141 received: _____

Flared Inlet Gas for: _____

Total MCF: _____

Briefly Describe Cause of Problem and action taken: _____

()
(Initials)