District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 HOBBS OCD Revised October 10, 2003

Submit 2 Copies to appropriate
DCT 2 3 2014 with Rule 116 on back
side of form

Release Notification and Corrective ActionRECEIVED

	OPERATOR Initial Report
Name of Company Southern Union Gas Services, Ltd.	Contact Crystal D. Callaway
Address 801 S. Loop 464, Monahans, TX, 79756	Telephone No. (817) 302-9407
Facility Name: Woolworth 12" (RP-1875) Lea County Field Dept.	Facility Natural Gas Gathering
Surface Owner Woolworth "Jal Library" Mineral Owner	: Fee Lease No. 30-025-23258
LOCATION OF RELEASE	
	h/South Line Feet from the East/West Line County
28 24S 37E	The state of the s
<u>Latitude N32 11.137 Longitude W103 09.778</u>	
NATURE OF RELEASE	
Type of Release Natural Gas and crude oil	Volume of Release 17 mcf Volume Recovered NONE natural gas and 12 bbls crude oil
Source of Release 12" Natural Gas Pipeline	Date and Hour of Occurrence Unknown Date and Hour of Discovery 3/1/08 Time: 8:00 a.m.
Was Immediate Notice Given? ☐ Yes ☒ No ☐ Not Require	If YES, To Whom?
By Whom?	Date and Hour:
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.
☐ Yes ⊠ No	
If a Watercourse was Impacted, Describe Fully,*	
Describe Cause of Problem and Remedial Action Taken: A 12" Natural gas pipeline operating at approximately 15 p.s.i. developed a leak, a repair crew excavated the leak area and installed a temporary repair clamp on 3/1/08. The line was permanently repaired on 3/20/08 by inserting approximately 500 ft. of 8" poly-pipe indside the existing 12" steel line. Describe Area Affected and Cleanup Action Taken. The leak site was discovered by Tony Savoie on 6/4/08 an ESA was performed and a remediation	
plan was prepared. Approximately 1,580 Sq. ft. of pasture was affected by the release and repair activities. All remediation activities will follow the NMOCD guidelines.	
Between June 10, and June 25, 2010, Basin Environmental remediated the Woolworth 12" Release Site. Confirmation soil samples were collected from the excavation floor and sidewalls prior to backfilling. Beginning June 19, 2008, the excavation was backfilled with treated material from SUG's Landfarm.	
Please see the attached Basin Environmental Services Technologies Remediation Summary and Site Closure Request for details of remedial	
activities and laboratory analytical results from confirmation soil sampling.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
reaction, state, of occur laws after or regulations.	OIL CONSERVATION DIVISION
Signature: (MATALD) Callauron	
Printed Name: Crysta D. Callaway	Approved by District Supervisor: Fail Spealer
Title: Senior Environmental Remediation Specialist	Approval Date: 10-27-14 Expiration Date:
E-mail Address: Crystal.Callaway@Regencygas.com	Conditions of Approval:
Date:10/08/2014 Phone: (817) 302-9407	IRO-1875