

HOBBS OGD

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

NOV 03 2014  
State of New Mexico  
Energy Minerals and Natural Resources

RECEIVED  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Regency Field Services LLC.	Contact: Crystal Callaway
Address: 301 Commerce St., Suite 700 Fort Worth, TX 76109	Telephone No.: (817) 302-9407
Facility Name: Trunk "O" Drip Tanks	Facility Type: Natural Gas Gathering
Surface Owner	Mineral Owner
API No.	

### LOCATION OF RELEASE

Unit Letter H	Section 28	Township 20 S	Range 37 E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.544504 Longitude -103.248805

### NATURE OF RELEASE

Type of Release: Unknown	Volume of Release: Unknown	Volume Recovered: Unknown
Source of Release: Trunk "O" Drip Tanks	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: Unknown
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Unknown	Date and Hour: Unknown	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
<p>The Trunk "O" Drip Tanks were removed and there was visual confirmation of a leak. The area affected measures approximately thirty (30) feet in length and twenty three (23) feet in width. Samples will be collected in order to delineate both vertically and horizontally. Soils with concentrations more than the NMOCD regulatory standards will be excavated and transported to a proper disposal facility. The site will be backfilled with clean material and the surface restored.</p>		
Describe Area Affected and Cleanup Action Taken.*		
<p>I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.</p>		

### OIL CONSERVATION DIVISION

Signature: <i>Crystal Callaway</i>	Approved by Environmental Specialist:	
Printed Name: <i>CRYSTAL CALLAWAY</i>	Approval Date: <i>11-7-15</i>	Expiration Date: <i>1-3-15</i>
Title: <i>Env. Enforcement Spec.</i>	Conditions of Approval:	
E-mail Address: <i>Crystal.Callaway@Regency.com</i>	<i>Site Supply report</i> <i>Revised 2/1/15 as per NMOCD</i> <i>gunk. Submit final C-141 by</i> <i>1-3-15</i>	
Date: <i>11/3/14</i>	Phone: <i>2178076514</i>	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

*ogrid. 298751*  
*f701430736121*  
*1701430736266*  
*p701430736309*

NOV 04 2014