District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources JAN 3 1 2013

RECEIVED

Form C-141 Revised October 10, 2003

Oil Conservation Division NMOCD ARTES Sabmit 2 Copies to appropriate District Office in accordance 1220 South St. Francis Dr.

with Rule 116 on back side of form

Santa Fe, NM 87505 **Release Notification and Corrective Action**

		OPEI	RATOR		Initi	al Report 🛮 🛛 Fina	l Repoi	
Name of Company BOPCO, L.P.	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	ony Savoie						
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 8	Telephone No. 432-556-8730							
Facility Name: Poker Lake Unit Well #205 at Battery PL	U-158	Facility Ty						
Surface Owner: Federal Mineral	Federal	Federal Lease No.						
LOC	CATIO	N OF REI	LEASE			•		
Unit Letter A Section 7 Township Range 30E Feet from the	North	/South Line	Feet from the	East/\	West Line	County Eddy		
<u>Latitude</u> 1	N32.237	400 Lon	gitude W103	.914150			-,	
NA	TURE	OF RELI	EASE					
Type of Release: Crude Oil	Crude oil							
Source of Release: 2 7/8" flow line	8/22/11, He	Date and Hour of Occurrence 8/22/11, Hour Unknown			Date and Hour of Discovery 8/22/11 8:54 a.m.			
Was Immediate Notice Given? ☑ Yes ☐ No ☐ Not I	Required	If YES, To	Whom?					
By Whom? Tony Savoic	Date and Hour: 8/22/11 1:00 p.m.							
Was a Watercourse Reached? ☐ Yes ☒ No			If YES, Volume Impacting the Watercourse.					
If a Watercourse was Impacted, Describe Fully.*		·						
Describe Cause of Problem and Remedial Action Taken: A flocular was installed on the line.	w line fro	om the PLU-20	05 pumping we	ll develop	oed a leak a	t the PLU-158 Battery, a	repair	
Describe Area Affected and Cleanup Action Taken.* Approxim picked up with a vacuum truck. A remediation plan will be devel	nately 300 loped in a) sq. ft. of pas secordance wit	ture land on the h the NMOCD	north sid	le of the ba I remediation	ittery pad, all of the free on guidelines.	oil was	
Remediation activities conducted at the Poker Lake Unit Well a meeting between BOPCO and NMOCD Representatives. Soil NMOCD-approved laboratory. On September 7, 2012, an NM September 7 and September 11, 2012, approximately 240 cy of Prior to backfilling, the final dimensions of the excavation were a	samples OCD-app f impacte	collected from roved polyured soil was exe	n the floor and ethane liner wa cavated and tra	l sidewal s installe nsported	Is of the ead in the flo to an NMC	ceavation were analyzed for of the excavation. Bo	by an etween	
Please reference the attached Basin Environmental Services' remediation activities.	Technolo	gies <i>Remedia</i>	tion Summary o	and Risk	-Based Site	Closure Request for det	ails of	
I hereby certify that the information given above is true and coregulations all operators are required to report and/or file certa public health or the environment. The acceptance of a C-141 r should their operations have failed to adequately investigate and or the environment. In addition, NMOCD acceptance of a C-federal, state, or local laws and/or regulations.	in release eport by I remediat	notifications the NMOCD te contaminati	and perform commerked as "Fin on that pose a t	orrective al Report hreat to g	actions for " does not ground wate	releases, which may end relieve the operator of li er, surface water, human	danger jability health	
20			OIL CONSERVATION DIVISION					
Signature: / Ora Dunne			Approved by District Supervisor:					
Printed Name: Tony Savoic			11/2/11/1					
Title: Waste Mgmt. & Remediation Specialist A			Approval Date: 10/29/19 Expiration Date: /VIII					
E-mail Address: TASavoie@BassPet.com		Conditions of a	Approval:	CN.	l			
Date: Phone: 432-556-8730		· · · · · · · · · · · · · · · · · · ·	<u> </u>	1100		200 05		
						akr-90	\Box	