

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OCD**  
State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

DEC 10 2014

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Yates Petroleum Corporation	Contact Bob Asher
Address 104 S. 4 <sup>th</sup> Street	Telephone No. 575-748-1471
Facility Name Mango BRM State #1H	Facility Type Battery

Surface Owner State	Mineral Owner State	API No. 30-025-40517
------------------------	------------------------	-------------------------

**LOCATION OF RELEASE**

Unit Letter C	Section 27	Township 20S	Range 35E	Feet from the 100	North/South Line North	Feet from the 2310	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.55103 Longitude 103.44576

**NATURE OF RELEASE**

Type of Release Crude Oil	Volume of Release 10 B/O	Volume Recovered 5 B/O
Source of Release Supply line	Date and Hour of Occurrence 11/17/2014; AM	Date and Hour of Discovery 11/17/2014; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The supply line was frozen, causing the release. Wells were shut off and vacuum truck(s) were called.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 50' X 200' on production pad and 90' x 300' (overspray/off pad). Production equipment was shut off and vacuum trucks were called to remove remaining oil. Impacted soils will be scraped and hauled to a NMOCD approved facility. Vegetation on overspray area will be Micro Blazed. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX. If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. **Depth to Ground Water: 50-99' (approximately 70' per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Asher	Approved by Environmental Specialist:	
Title: NM Environmental Regulatory Supervisor	Approval Date: <u>12-10-15</u>	Expiration Date: <u>2-10-15</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval:	
Date: December 8, 2014	Phone: 575-748-4217	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

*Site Sample request*  
*RRP- Determine & remediate area on pad*  
*to NMOCD guide, submit Final C-141 by 2-10-15*  
*ogm 25575*  
*77014 3442 9856*  
*PTO 14 7443 0069*

DEC 11 2014