

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBSOCD**

**DEC 10 2014**

**RECEIVED**

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Lightning 1 State SWD #1	Facility Type: SWD

Surface Owner: State	Mineral Owner:	API No. 30-025-40917
----------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	I	21S	33E	3480'	South	2300'	West	Lea

Latitude 32.5100979643208 Longitude -103.527106855718

**NATURE OF RELEASE**

Type of Release: Oil and Produced Water	Volume of Release: 21 bbls Oil; 665 bbls PW	Volume Recovered: 20 bbls Oil; 664 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 12/3/2014 8:00 pm	Date and Hour of Discovery: 12/3/2014 8:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 12/5/2014 1:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
This release was caused by a transfer pump pressuring up and causing connections to fail. Vacuum trucks were dispatched and all standing fluid was recovered and disposed of at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.\*  
This release occurred within a lined facility. After the standing fluid was recovered, repairs were made and the facility cleaned.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 12-10-14	Expiration Date: -
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: December 5, 2014 Phone: 575-748-6940		IRP- 3448

\* Attach Additional Sheets If Necessary

229137

270 19 344 8865  
P 70 14 34 439009

**DEC 11 2014**