

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OGD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Resolute Natural Resources Co, LLC	Contact: Patrick Flynn	
Address: 1700 Lincoln Street Suite 2800, Denver, CO 80203	Telephone No. 303.534.4600 X1145	
Facility Name: State A Tank Battery	Facility Type: Tank Battery	
Surface Owner	Mineral Owner	API No.: 30-025-05245

LOCATION OF RELEASE

Unit Letter	Section 2	Township 15S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude: 33.04461N Longitude: 103.17622W

NATURE OF RELEASE

Type of Release: Produced water and oil	Volume of Release: 238 Bbl water and 42-Bbl oil	Volume Recovered: 204 Bbl water and 36 Bbl oil
Source of Release: Overran water tank	Date and Hour of Occurrence:	Date and Hour of Discovery: 12/12/14 @ 8:30AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Water transfer pump failed, as did the in-field telemetry, allowing the water tank to over fill into the secondary containment area.

Describe Area Affected and Cleanup Action Taken.*

All released fluids were contained within the secondary containment berm. A vacuum truck was used to recover most of the fluid released. The recovered water was taken to the Gandy Marley facility for disposal and oil was returned to the production tank. Affected pea gravel and soil will be excavated for offsite disposal at the Gandy Marley landfarm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature

Printed Name: Patrick Flynn

Title: Vice President

E-mail Address: pflynn@resoluteenergy.com

Date: 12/15/14

Phone: 303.534.4600 X1145

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

Approval Date: 12-15-14

Expiration Date: 2-15-15

Conditions of Approval:

Site Super reports Release &
conditions to NMOCD quarterly
Submit for C-141 by 2-1-15

Attached ☐

IRP-3458

295770

DEC 15 2014

070143494 57784
070143494 5623