

# NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240

District II  
811 S. First St., Artesia, NM 88210

District III  
1000 Rio Brazos Road, Aztec, NM 87410

District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

DEC 08 2014

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

## FA131434934765 Release Notification and Corrective Action

11AB1434934919

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Transwestern Pipeline	Contact: Kevin Koerber
Address: 2605 W Main, Artesia, NM 88210	Telephone No.: (505) 227-4008
Facility Name: Atoka Lateral River Block Valve	Facility Type: Natural Gas Pipeline

Surface Owner	Mineral Owner	API No.
---------------	---------------	---------

### LOCATION OF RELEASE

Unit Letter	Section 12	Township 18S	Range 26E	Feet from the	North/South Line	Feet from the	East/West Line	County
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------

Latitude 32.761694 Longitude -104.338557

### NATURE OF RELEASE

Type of Release: Pipeline Quality Natural Gas	Volume of Release: 164.7mcf	Volume Recovered: 0 mcf
Source of Release: Pipeline Blowdown Riser	Date and Hour of Occurrence: 5 December, 2014 10:00 am	Date and Hour of Discovery: 5 December, 2014 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy Dade	
By Whom? Kevin Koerber	Date and Hour: 11:45 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 0 mcf	

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*


Line needed to be blown down for excavation to conduct pipe inspection.

Describe Area Affected and Cleanup Action Taken.\*

No area affected, and no cleanup actions taken

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: 
Printed Name: Kevin L. Koerber
Title: Station Operator
E-mail Address: Kevin.Koerber@energytransfer.com
Date: 8 Decmeber, 2014 Phone:(505) 227-4008

Signed By: <u><i>[Signature]</i></u>	
Approved by Environmental Specialist: _____	
Approval Date: <u>12/10/14</u>	Expiration Date: <u>N/A</u>
Conditions of Approval: <u>FINAL</u>	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2RP-2654