District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Minerals and Natural Resources

Oil Conservation Division **DEC 1 6** 2014220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

, Release Motification and Corrective Action

No of Co			<u> </u>					☐ Final Repor				
Name of Co		n Gas Services,		ContactCrystal CallawayTelephone No.(817) 302-9407								
Address 801 S. Loop 464, Mo Facility Name: Pipeline #101						Facility Type			(817) 302-9407 Natural Gas Gathering			
Surface Owner Crawford Mineral Owner:						Lease No. 30-025-38822						
				····		N OF RE	LEASE					
Unit Letter Section Township Range I P 20 24S 37E				Feet from the	North	/South Line	Feet from the	East/West Line		County Lea		
Latitude N32 degrees 11.749' Longitude W103 degrees 10.788'												
				NAT	URF	OF REL	EASE					
Type of Release Crude Oil, Produced Water and Natural Gas Volume of Release: 7BBLS Volume Recovered: 4 BBLS											BBLS	
Source of Release 16-Inch Steel Pipeline						Date and Hour of Occurrence January 25, 2011 – Time Unknown			Date and Hour of Discovery January 25, 2011 – approximately 1200 hrs			
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required						If YES, To Whom?						
By Whom? Curt Stanley							Date and Hour:					
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.					
☐ Yes ☒ No												
If a Watercou	urse was Im	pacted, Descr	ibe Fully.									
standing flui Following th will be made Describe Are The release a completion of	ds from the initial restance. a Affected affected and permanen	e ground suri ponse activiti and Cleanup a area measurin t pipeline repa	face. Follows, the exoretion Tales approximate activition	cavation was back cavation was back cen. mately 1,700 squ es.	ation of kfilled of are feet	f the pipeline, due to the pro	, a temporary pip ximately of the re will be remediate	d per N	elamp was o a county	utilized to road. Perman	ralled to recover free mitigate the release. nent pipeline repairs delines following the all dimensions of the	
excavation w BTEX, TPH	Between February 28, and March 8 2013, approximately 408 yd ³ of impacted material was excavated from the location. The final dimensions of the excavation were approximately 45' x 15' x 15'. Soil samples collected from the excavation floor and sidewalls indicated concentrations of Benzene BTEX, TPH and chloride were less than NMOCD Regulatory Standards. Please see the attached Basin Environmental Services Technologies Remediation Summary and Site Closure Request for details of remedial activities and the site investigation.											
I hereby cert regulations a public health should their or the enviro	ify that the all operators or the envious operations on the comment. In	information are required ironment. The have failed to	given abo to report le accepta adequatel IOCD acc	ve is true and comend/or file certainnee of a C-141 rely investigate and	mplete in release eport by remedi	to the best of se notification the NMOCI take contaminate contaminate.	my knowledge a as and perform co D marked as "Fina ation that pose a t	nd und orrective al Repo hreat to	erstand that e actions for ort" does not ground wa	or releases, vot relieve the ater, surface	NMOCD rules and which may endanged operator of liability water, human health ance with any other	
Signature: Cural Callans 21						OIL CONSERVATION DIVISION						
Printed Name: Crystal Callaway							Approved by District Supervisor:					
Title: Sr. EHS Compliance Specialist						Approval Da	ite: 12-16-14	•	Expiration	Date:		
E-mail Address: Crystal.Callaway@Regencygas.com						Conditions of	of Approval:	oval:				
Date: 12/01/2014 Phone: (817) 302-9407								IRP 2677				