

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

PAB1435739361

Release Notification and Corrective Action

NAB1431332210

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Enterprise Field Services LLC	Contact	Dina Babinski
Address	PO Box 4324, Houston TX 77252	Telephone No.	210-528-3824
Facility Name	Pipeline ROW, 1003 Gathering Lateral	Facility Type	Gas Gathering Pipeline

Surface Owner	Private Owner	Mineral Owner	NA - Pipeline	API No.	NA
---------------	---------------	---------------	---------------	---------	----

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	35	24S	28E	398	North	579	East	Eddy

Latitude N 32.1801 Longitude W -104.0513

NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release	1,000 MCF	Volume Recovered	NA
Source of Release	Pipeline Blowdown, Overpressure	Date and Hour of Occurrence	12/11/2014 @ 5:00 MST	Date and Hour of Discovery	12/11/2014 @ 15:00 MST
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, NMOCD		
By Whom?	Osman De Leon	Date and Hour	12/11/2014 @ 15:30 MST		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

NM OIL CONSERVATION

ARTESIA DISTRICT



DEC 23 2014

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*
Due to downstream flow restrictions, pipeline pressure above the maximum allowable operating pressure required pipeline blowdown to relieve pressure in an effort to prevent potential pipeline failure and additional gas releases.

Describe Area Affected and Cleanup Action Taken.*
The pipeline blowdown was performed to relieve pressure from the system. No liquid spills occurred requiring any cleanup actions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jon E. Fields	Approved by: 	
Title: Director, Field Environmental	Approval Date: 12/23/14	Expiration Date: 12/1/15
E-mail Address: jefields@eprod.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 12-18-2014 Phone: 713-381-6684		

\* Attach Additional Sheets If Necessary

2RP-2694



ENTERPRISE PRODUCTS PARTNERS L.P.  
ENTERPRISE PRODUCTS HOLDINGS LLC  
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

December 18, 2014

**NM OIL CONSERVATION**  
ARTESIA DISTRICT  
DEC 23 2014

Mr. Mike Bratcher  
New Mexico Oil Conservation Division  
District 2 Office  
811 South First Street  
Artesia, New Mexico 88210

RECEIVED

**RE: Form C-141 Report for Enterprise Field Services LLC  
Releases on Carlsbad Area Gathering Lines**

Dear Mr. Bratcher:

Enclosed, please find the required C-141 Form for the unplanned blowdown on our 1003 Line in Eddy County on December 11, 2014. The pipeline was blown down to relieve pressure from the system and prevent damage to the pipeline and potential gas leaks. This report is sent to follow-up on the immediate verbal notification by Osman De Leon on December 11, 2014 at 15:30 MST and NMAC 19.15.29 requirements.

If you have any questions or need additional information, please contact Dina Babinski, our area Environmental Supervisor by phone at 210-528-3824 or via email at [djbabinski@eprod.com](mailto:djbabinski@eprod.com) or me at 713-318-6684.

Regards,

Jon E. Fields  
Director, Field Environmental