District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Name of Company: ConocoPhillips

HOBBS OCD State of New Mexico Energy Minerals and Natural Resources

JAN 0 7 205 il Conservation Division 1220 South St. Francis Dr.

RECEIVED Santa Fe, NM 87505

Form C-141 Revised August 8, 2011

P101500735485

Final Report

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Initial Report

Release Notification and Corrective Action

OPERATOR

Contact: Spencer Cluff

Address: 1410 N West Country Road						Telephone No. 575-746-7248					
Facility Name: Meyer B-31 #006						Facility Type: Well					
Surface Owner: NMOCD Mineral Owner: BLM API No. 30-025-35143										. 30-025-35143	
LOCATION OF RELEASE											
Unit Letter	Section										
С	31	20S	38E	990	North		1980	West		LEA	
Latitude 3	Latitude 32.5340512374022,- Longitude 103.189949326107										
NATURE OF RELEASE											
Type of Release: Spill										Volume Recovered: 0 BBLS	
Source of Release: Flow Line						Date and Hour of Occurrence 12/29/2014 7:00 am				Hour of Discovery 14 12:00 pm	
							If YES, To Whom?				
Yes No Not Required Tomas Oberding											
							olomon Hughes				
By Whom? Spencer Cluff Date and Hour: 12/31/2014 11:00 am Was a Watercourse Reached? If YES, Volume Impacting the Watercourse.											
Yes No							11 125, Volume Impacting the Watercourse.				
If a Watercourse was Impacted, Describe Fully.*											
Describe Cause of Problem and Remedial Action Taken.*											
On Monday, December 29, 2014 at 1200 hrs. MST an agency reportable spill occurred at the Myers B-31 when a circulating line froze and split. Spill area covered 42 ft X 90 ft and 1" deep, totaling 5.5 BO with 2 BO recovered. MSO notified Supervisor, installed a temporary clamp, and shut the valves to stop the leak. A work order has been submitted to remediate the area and repair the line. The spill will be remediated according to NMOCD guidelines. This is not a PSE.											
Describe Area Affected and Cleanup Action Taken.* MSO notified Supervisor, installed a temporary clamp, and shut the valves to stop the leak. A work order has been submitted											
to remediate the area and repair the line. The spill will be remediated according to NMOCD guidelines. This is not a PSE.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
						OIL CONSERVATION DIVISION					
Signature: Spencer A. Cluff											
Printed Name: Spencer A. Cluff						Approved by Environmental Specialist:					
				-				•			
Title: LEAD	HSE					Approval Dat	e: 1-7-15]	Expiration	Date: 3-7-15	
E-mail Addre	ess: spen o	cer.a.cluff@	@conoco	ophillips.com	,	Conditions of	Syph reguel	r Roli N noc	ele O guli	Attached	
Date: 12/31/2	2014		1	Phone:575-746-72	248	man m	£ C-HILY 3-	7-15		IRP-3484	
Attach Addi		ets If Necess								11Kp-7401	
			•				JAN 0	8 29	0 15	Ato 1500 7 35303	