District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Title: LEAD HSE

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15,29 NMAC.

Form C-141

JAN 97 20 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action												
			-	KECEIAED	ad i	<b>OPERA</b>	ГOR			al Report		Final Report
Name of Co	mpany: C	onocoPhilli	ps			Contact: Spencer Cluff				1		<u> </u>
Address: 14			Telephone No. 575-746-7248									
						Facility Type: Battery						
Surface Owner: NMOCD Mineral Owner:												
Surface Ow	ner: NWO	BLM API No. 30-025-06239										
LOCATION OF RELEASE												
Unit Letter J	Section	Township	Range	Feet from the		South Line	Feet from the	l .	Vest Line	County		
	23	20S	37E	1980	South		1980	East		LEA		
Latitude 32.5567134268039,- Longitude 103.220020515971												
NATURE OF RELEASE												
Type of Release: Spill Volume of Release: 15.67 BBLS Volume Recovered: 0 BBLS  Source of Release: Flow Line Date and Hour of Occurrence Date and Hour of Discovery												
Source of Ker	iease: riow	Line				Date and Hour of Occurrence Date and Hour of Discovery 3112/2014 4:20 am 3112/2/2014 5:00 am						
Was Immedia	ate Notice C	Given?				If YES, To Whom?						
		$\boxtimes$	Yes 🛛	No 🔲 Not Red	quired	Tomas Oberding						
D 11/1 0.0		oe .				Solomon Hughes						
By Whom? Spencer Cluff Was a Watercourse Reached?						Date and Hour: 12/31/2014 12:00 am  If YES, Volume Impacting the Watercourse.						
was a watercourse Reacned?  ☐ Yes ☒ No						li i LS, ve	nume impacting t	ne wate	ercourse.			,
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.*												
On Wednesday, December 31, 2014 at 0420 hrs. MST, an agency reportable spill occurred at the SEMU 95 SWD when the skim over flowed. MSO received a high level alarm at 0400 hrs. MST and then a high high level alarm at 0420 hrs. MST. MSO responded to high level alarm by going out to location. MSO shut down the wells to the SEMU 95 SWD and closed the inlet valve to stop the leak. Upon further inspection, MSO noticed that the u-tube was frozen and caused the surge tank to fill and send fluid to the skim tank. MSO also noticed that the surge valve was frozen open causing the actuator to stay open and fill the surge tank.												
Describe Are	ea Affected	d and Cleani	up Action	Taken.*								
The spill area was 150 ft X 225 ft. X 0.5 deep and resulted in 3 BO and 12.67 BPW for a total of 15.67 bbls of total fluid, with none recovered. This is a PSE Tier 2. The spill will be remediated according to NMOCD guidelines.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
··				-			OIL CON	SERV	<b>ATION</b>	DIVISIO	<u>NC</u>	
Signature: S	housen A Do.	.,,,			.						-	
					-	Approved by	Environmental S	pecialis	t:			
Printed Name	: Spencer A	a. Cluff										

Approval Date: 1-7-15

Expiration Date: 3-7-15

E-mail Address: <b>spencer.a.clu</b>	uff@conocophillips.com	Conditions of Approval:  Sile Supla require.  Debute & radite are as per	Attached
Date: 12/31/2014	Phone:575-746-7248	Noto Co quile. Salut for	IRP 3485
* Attach Additional Sheets If Neo	cessary	(-141 by 3-7-15	21781

NTO 15007 38356 P7015007 38845