

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
HOBBS
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RELEASE Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Spencer Cluff	
Address: 1410 N West Country Road	Telephone No. 575-746-7248	
Facility Name: Warren Unit Satellite 5	Facility Type: Satellite	
Surface Owner: NMOCD	Mineral Owner: BLM	API No. 30-025-30473

LOCATION OF RELEASE

Unit Letter F	Section 28	Township 20S	Range 38E	Feet from the 1940	North/South Line North	Feet from the 2020	East/West Line West	County LEA
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	----------------------

Latitude 32.5462164601454 Longitude 103.155469948588

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 15.67 BBLs	Volume Recovered: 0 BBLs
Source of Release: transfer pump intake line	Date and Hour of Occurrence 01/03/2015 7:30 am	Date and Hour of Discovery 01/03/2015 1:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding Solomon Hughes	
By Whom? Spencer Cluff	Date and Hour: 01/05/2015 12:15 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

On Saturday, January 3, 2015 at 1330 hrs. MST, a spill occurred at the Warren Unit Satellite 5. The spill originated from the transfer pump intake line. All valves were closed to the transfer pump and separator, and the transfer pump power was also disabled at the electrical box. Spill area was 120 ft. x 60 ft. x 1 inch deep for a total of 6.68 BO with none recovered. The spill remained on the caliche pad. The area will be remediated according to NMOCD guidelines.

Describe Area Affected and Cleanup Action Taken.*

Spill area was 120 ft. x 60 ft. x 1 inch deep for a total of 6.68 BO with none recovered. The spill remained on the caliche pad. The area will be remediated according to NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Spencer A. Cluff		OIL CONSERVATION DIVISION	
Printed Name: Spencer A. Cluff		Approved by Environmental Specialist:	
Title: LEAD HSE		Approval Date: 1-7-15	Expiration Date: 2-7-15
E-mail Address: spencer.a.cluff@conocophillips.com		Conditions of Approval: <i>Side Spill - pad. Delude & remove area as per NMOCD guide which find C-141 37-15.</i>	Attached <input type="checkbox"/> IRP-3486
Date: 01/05/2015	Phone: 575-746-7248		

* Attach Additional Sheets If Necessary

JAN 08 2015

217817
NT 015007 57228
PT 015007 57372