

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505
JAN 12 2015
RECEIVED

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Spencer Cluff	
Address: 1410 N West Country Road	Telephone No. 575-746-7248	
Facility Name: SEMU 180	Facility Type: Well	
Surface Owner: NMOCD	Mineral Owner: BLM	API No. 30-025-39189

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	13	20S	37E	2139	South	501	West	LEA

Latitude 32.5717013416412 Longitude 103.211970896631

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 6.57 BBLS	Volume Recovered: 3 BBLS
Source of Release: transfer pump intake line	Date and Hour of Occurrence 01/09/2015 7:30 am	Date and Hour of Discovery 01/09/2015 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding Solomon Hughes	
By Whom? Spencer Cluff	Date and Hour: 01/12/2015 10:35 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

ENV - Agency Reportable - 6.57 BBLS - SEMU 180 - RR II - MCBU - Hobbs: On Friday, January 9, 2015 a leak at the SEMU 180 occurred. A valve on production tubing was open and pressure gauge froze, spilling fluid on the ground.

Describe Area Affected and Cleanup Action Taken.*

The spill area was 32 ft. x 60 ft. x 2 inches in depth with 3 bbls recovered for a total of 6.57 bbls. The 3 bbls recovered were 1 BPW and 2 BO. This spill remained on the caliche pad. The area will be remediated according to NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Spencer A. Cluff</i>		OIL CONSERVATION DIVISION	
Printed Name: Spencer A. Cluff		Approved by Environmental Specialist:	
Title: LEAD HSE		Approval Date: 1-12-15	Expiration Date: 3-12-15
E-mail Address: spencer.a.cluff@conocophillips.com		Conditions of Approval: <i>Site Supervisor report details Remediate area per NMOCD guidelines Submit final C-141 by 3-12-15</i>	
Date: 01/09/2015 Phone: 575-746-7248		Attached <input type="checkbox"/> IRP-3500	

* Attach Additional Sheets If Necessary

JAN 13 2015

7701501240426
P701501241144