

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OGD State of New Mexico  
JAN 13 2015 Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
RECEIVED

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Jesse A. Sosa
Address	3300 North A St., Bldg. 6, Midland, TX 79705-5406	Telephone No.	505.391.3126
Facility Name	Wilder Process Facility	Facility Type	Oil and Gas

Surface Owner	BLM	Mineral Owner	BLM	Lease No	38787
---------------	-----	---------------	-----	----------	-------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	28	26S	32E	610	N	835	E	Lea

Latitude 32 1 15 N Longitude 103 41 20 W

#### NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
vapor	.01bbl (.01oil, 0water)	(0oil, 0water)
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
unknown	1/8/15 10 am	1/8/15 10 am
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Tomas Oberding NMOCD & Jim Amos BLM	
By Whom?	Date and Hour	
Jesse Sosa	1/9/15 & 1/12/15 2:26 pm & 2:56 pm	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

A rental compressor located at the Wilder Process Facility went down at approximately 10 am on 1/8/2015. Technician went to the compressor to investigate and heard a loud pop followed by a flash fire at the electrical panel.

Describe Area Affected and Cleanup Action Taken.\*

Property damage was restricted to electrical panel at compressor and immediate location. No fluid was released.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Jesse A. Sosa		Approved by District Supervisor: 	
Title: HSE Lead		Approval Date: 1-13-15	Expiration Date: —
E-mail Address: Jesse.A.Sosa@conocophillips.com		Conditions of Approval: —	Attached <input type="checkbox"/>
Date: 1/12/2015	Phone: 505.391.3126	1RP-3802	

• Attach Additional Sheets If Necessary

JAN 13 2015

FTO 1501330167  
PTO 1501330344  
NTO 15 01330484

217817