District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Pto 15008 34348

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

					<i>1</i> 11100 1	C, 14141 075	/03						
Release Notification and Corrective Action													
							OPERATOR			al Report		Final Report	
Name of Company- Harvey E. Yates Company							OPERATOR Initial Report Final Contact- Tammy R. Link						
							Telephone No. 575-623-6601						
						Facility Type - API #30-025-28889							
Surface Owner - Fee Mineral Owner							API No. 30-025-28889						
			······································			NI OP DE	I TRACIE		1	. 50 020 2	.000	** ***	
Unit Letter	Section	Township	Range	Feet from the		N OF RE	Feet from the	Fast/V	Vest Line	County			
K	1	18S	32E	1980'	ivoru	S			W	Lea			
											· · · · · · · · · · · · · · · · · · ·		
LatitudeLongitude													
NATURE OF RELEASE													
Type of Release - 57 bbls total fluid							Volume of Release - 57 bbls Volume Recovered 35 bbls						
Source of Release							Date and Hour of Occurrence Date and Hour of Discovery-1					-1/5/15 7:15	
Fire tube gasket blew and caused release							r 5:00 pm	am					
Was Immediate Notice Given? ☑ Yes ☐ No ☐ Not Required							If YES, To Whom? Tomas Oberding Bill with OCD in Hobbs						
By Whom? Keith Cannon							Date and Hour 1/5/15 at 10:45 am						
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
☐ Yes ☒ No													
If a Watercon	ırse was İmp	acted, Descr	ibe Fully.	*									
HOBBSOCD													
Describe Co.	see of Proble	m and Dama	dial Actio	n Takan *			- IAIN	0.0					
Describe Cause of Problem and Remedial Action Taken.* Fire tube gasket blew							JAIN @ 8 2015						
D	- A CCA - 1	1.01								 			
Describe Area Affected and Cleanup Action Taken.* Replace fire tube gasket and											,		
steam clean heater treater and spray with overspray in pasture w/1000 gals of water 3% microblaze.													
I hereby certi	fy that the ir	oformation gi	ven above	e is true and comm	lete to	the best of my	knowledge and u	understar	nd that pur	suant to NM	IOCD r	ules and	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
				stance of a C-141	report	does not reliev	e the operator of	responsi	ionity for c	omphance	with an	y omer	
federal, state, or local laws and/or regulations.							OIL CONSERVATION DIVISION						
Signature any R. Tit													
							Approved by Environmental Specialist:						
Printed Name:Tammy R. Link							-Environmental S	Specialist	t:				
							1						
Title: Engineering Tech							Approval Date: 1-8-15			Expiration Date: 3-8-15			
E-mail Addre	ess: tlink@h		Conditions of Approval:				Attache	ı 🗆					
Doto: 1/4	5/15		Dhana	575-623-6601	Enders men a pa NAOCA Junto. Schrift Fil C-191 13			duli	12P -3 788				
Date: 1/6 * Attach Addi		te If Nacass		77-043-0001		Crante	ie man as a	a NM	OCD	104			
Auacii Audi	uonai onee		grande. Jakit Fil C-141 4										
							- 21-81	- //	ク	NTO 1	500	8 34175	