

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**HOBBSOCD**

Form C-141  
Revised August 8, 2011

**JAN 15 2015**

Submit 1 copy to appropriate District Office in accordance with 19.15.29 NMAC.

**RECEIVED**

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company <i>Roswell Operating, LLC</i>	Contact <i>Todd Yocham</i>	
Address <i>P.O. Box 351 Midland, TX 79702</i>	Telephone No. <i>432-770-0615</i>	
Facility Name <i>SAWYER TANK BATTERY (CS04)</i>	Facility Type <i>Production Battery</i>	
Surface Owner <i>David Williams</i>	Mineral Owner <i>various</i>	API No.

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>I</i>	<i>27</i>	<i>09S</i>	<i>36E</i>	<i>1980</i>	<i>South</i>	<i>1200</i>	<i>East</i>	<i>Lea</i>

Latitude *33.5033638* Longitude *-103.2390717*

**NATURE OF RELEASE**

Type of Release <i>Tank rupture</i>	Volume of Release <i>390 bbl</i>	Volume Recovered <i>350 bbl</i>
Source of Release <i>Freeze up due to icy weather</i>	Date and Hour of Occurrence <i>1/4/15</i>	Date and Hour of Discovery <i>1/4/15 AM</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>10 AM</i>	<i>10</i>
By Whom? <i>Merch Merchant</i>	<i>OCD - Hobbs, NM</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour <i>1/4/15 11 AM</i>	If YES, Volume Impacting the Watercourse.

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* *A FWKO vessel had a line rupture due to ice freeze up. The resulting rupture ignited and a fire ensued. The fire burned off the oil and the produced water was contained inside the fire wall. The resultant water inside the fire wall was removed with vacuum trucks and properly disposed.*

Describe Area Affected and Cleanup Action Taken.\* *The area affected is ~ 200' x 200' inside the bermed fire walls. The released produced water was removed with vacuum trucks and the area inside the fire walls will be remediated and the production battery will be rebuilt.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Todd M. Yocham</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Todd M. Yocham</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <i>Exec. V.P.</i>	Approval Date: <i>1-15-15</i>	Expiration Date: <i>2-15-15</i>
E-mail Address: <i>tyocham@desertproduction.com</i>	Conditions of Approval: <i>Site system repair before production and as per NMOCD guide.</i>	Attached <input type="checkbox"/> <i>IRP-3507</i>
Date: <i>1/9/15</i> Phone: <i>432-770-0615</i>	<i>Submit final C-141 by 3-15-15</i>	

\* Attach Additional Sheets If Necessary

**JAN 15 2015**

*F701501550521*  
*N701501550859*  
*P701501551032*

*270575*