

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

JAN 16 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*NAB150214294*

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Marauder Federal #1H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-015-38244
------------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	31	19S	31E	330	North	660	West	Eddy

Latitude 32.6231450328974 Longitude -103.914919290024

**NATURE OF RELEASE**

Type of Release: Oil and Produced Water	Volume of Release: 15 bbls Oil; 10 bbls PW	Volume Recovered: 0 bbls Oil; 0 bbls PW
Source of Release: Flare	Date and Hour of Occurrence: 1/1/2015 12:00 am	Date and Hour of Discovery: 1/1/2015 12:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <i>25 bbl release Immediate</i>	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>Notification</i>	

*IS required!*

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by a problem at the battery that lead to fluid coming out the flare. Soapy water and Microblaze was applied to the impacted pasture and vegetation.

Describe Area Affected and Cleanup Action Taken.\*

The impacted area is located adjacent to battery and is approximately 300' x 600' in size. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>Huber</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>1/20/15</i>	Expiration Date: <i>NA</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: January 16, 2015 Phone: 575-748-6940	<b>Remediation per O.C.D. Rules &amp; Guidelines</b>	

\* Attach Additional Sheets If Necessary

**EMERGENCY REMEDIATION PROPOSAL NO**  
**LATER THAN: 2/20/15**

*2RP-2749*

## **Patterson, Heather, EMNRD**

---

**From:** Amanda Trujillo <ATrujillo@concho.com>  
**Sent:** Friday, January 16, 2015 2:55 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; james\_amos@blm.gov; jlrobertson@blm.gov  
**Subject:** (Notification/C-141 Initial) Marauder Federal #1H (30-015-38244)  
**Attachments:** 1-1-2015 Marauder Federal #1H (TB) Initial.pdf

Mr. Bratcher/Mr. Robertson,

COG Operating LLC is reporting a release on the Marauder Federal #1H (30-015-38244)  
Unit D Section 31, Township 19S Range 31E  
The release occurred at 12:00 am on 1/1/2015  
Released: 15 bbls Oil ; 10 bbls PW  
Recovered: 0 bbls Oil ; 0 bbls PW

The release was caused by an issue at the tank battery that caused fluid to be sent to the flare. I release impacted an adjacent pasture. Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

### **Amanda Trujillo**

Senior Environmental Coordinator  
COG Operating LLC  
Cell: 505.350.1336  
Office: 575.748.6930  
[atrujillo@concho.com](mailto:atrujillo@concho.com)

2208 W. Main St.  
Artesia , NM 88210



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained

herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.