

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1900 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	State of New Mexico Energy Minerals and Natural Resources Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505	Form C-141 Revised August 8, 2011 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
---	---	--

Release Notification and Corrective Action

OPERATOR		☒ Initial Report ☐ Final Report
Name of Company: Oxy USA Inc.		Contact: Austin Trammell
Address: 1017 W Stanelind Road		Telephone No.: 575-499-4919
Facility Name: Cotton Draw Unit 10		Facility Type: Well Location
Surface Owner: BLM	Mineral Owner:	API No.: 30-025-08195

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	16	25S	32E	660	N	660	E	Lea

Latitude: 32.13683° Longitude: -103.67362°

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 35BBL	Volume Recovered: 30BBL
Source of Release: 2" steel production line due to internal corrosion	Date and Hour of Occurrence: 04/01/2014 @ 2:00 PM	Date and Hour of Discovery:
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? Geoffrey Leking NMOCD, Jennifer Van Curen BLM	
By Whom? Austin Trammell	Date and Hour: 04/02/2014 @ 02:37 PM	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse: HOBBS OCD	
If a Watercourse was Impacted, Describe Fully: JAN 22 2015		
Describe Cause of Problem and Remedial Action Taken: Internal corrosion on a 2" steel production flow line cause 35 bbls of produced water to leak onto the ground. The well was recovered and well was shut in.		
Describe Area Affected and Cleanup Action Taken: The affected area is approximately 18'x40'. Remediation will be completed in accordance with an approved remediation plan from the NMOCD and the BLM.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: Printed Name: Austin Trammell Title: HES Specialist E-mail Address: Austin_trammell@oxy.com Date: 04/14/2014 Phone: 575-499-4919	OIL CONSERVATION DIVISION Approved by: Hydrologist Approval Date: 1-22-15 Expiration Date: _____ Conditions of Approval: _____ Attached ☐ R.P.-3278
--	--

* Attach Additional Sheets If Necessary

PFD14027067