ARTESIA DISTRICT District I State of New Mexico 1625 N. French Dr., Hobbs, NM 88240 Form C-141 IAN 1 9 2015 **Energy Minerals and Natural Resources** District II Revised August 8, 2011 811 S. First St., Artesia, NM 88210 District III Submit 1 Copy to appropriate District Office in Oil Conservation Division RECEING Dance with 19.15.29 NMAC. 1000 Río Brazos Road, Aztec, NM 87410 1220 South St. Francis Dr. District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 **Release Notification and Corrective Action** NAB 15020376.30 **OPERATOR** Initial Report Final Report IINAALA Name of Company Oxy USA Contact Tiffney Burkham Address 1502 W Commerce Telephone No. 575-706-3616 Facility Name Pure Gold B-4 Battery Facility Type Surface Owner Mineral Owner API No: 3001527238 LOCATION OF RELEASE Feet from the Feet from the Unit Letter Section Township Range North/South Line East/West Line County р 20 31E 660 23S S 660 E Eddy Latitude Longitude NATURE OF RELEASE Type of Release GAS Volume of Release 7.740MCF Volume Recovered O Source of Release Date and Hour of Occurrence Date and Hour of Discovery 1/5/2015 Was Immediate Notice Given? If YES, To Whom? Yes 🗋 No 🗋 Not Required Mike Bratcher By Whom? Tiffney Burkham Date and Hour Was a Watercourse Reached? If YES. Volume Impacting the Watercourse.  $\Box$  Yes  $\Box$  No If a Watercourse was Impacted, Describe Fully.\* Describe Cause of Problem and Remedial Action Taken.\* High gas line pressure caused by Enterprise Sand dune Compressor being shutdown. Describe Area Affected and Cleanup Action Taken.\* I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OII Signature: Signed By Approved by Environmental Species Printed Name: Tiffney Burkhan Expiration Date: N Title: HES Administrative Assistant Approval Date: E-mail Address: Tiffney\_burkham@oxy.com Conditions of Approval Attached -INAL Date: 1/19/2014 Phone: 575-628-4116 \* Attach Additional Sheets If Necessary 127-11

NM OIL CONSERVATION

## Bratcher, Mike, EMNRD

From:	Tiffney_Burkham@oxy.com
Sent:	Monday, January 19, 2015 7:59 AM
То:	Bratcher, Mike, EMNRD
Cc:	Benjamin_Watkins@oxy.com
Subject:	C141's Pure Gold D-1 Pure Gold B-4 & Federal 29-8 Mobil Federal Battery
Attachments:	Document.pdf

Mr. Bratcher,,

I have attached the C141's for these locations. Please let me know if you have any questions. Hope you have a great day!

Tiffney Burkham HES Administrative Assistant Permian Resources (O) 575-628-4116 (C) 575-706-4374 tiffney\_burkham@oxy.com

-----Original Message----From: Burkham, Tiffney M Sent: Monday, January 05, 2015 11:40 AM To: 'Bratcher, Mike, EMNRD' Cc: Watkins, Benjamin I; Tramell, Austin W Subject: C129 Pure Gold D-1 Pure Gold B-4 & Federal 29-8 Importance: Low

Mr. Bratcher,

This is to inform you that Oxy is flaring at the Federal 29-8, Pure Gold D-1 Battery & Pure Gold B-4. This is due to High gas line pressure caused by Enterprise Sand Dune Compressor being down. I have attached the C129's and will send out the C141 once we have stopped flaring. Let me know if you have any questions.

Tiffney Burkham HES Administrative Assistant Permian Resources (O) 575-628-4116 (C) 575-706-4374 tiffney burkham@oxy.com