State of New Mexico Energy Minerals and Natural Resources RECEIVED

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr.

JAN 2 3 2013 ubmit 2 Copies to appropriate District Office in accordance NMOCD ARTESIA with Rule 116 on back side of form

| 1220 S. St. Frai | ncis Dr., San | ta re, NM 8/50 | 5 | Sa | anta F | e, NM 875 | 505 | | | | | side of form |
|--|---------------|------------------|-------------|---|----------|--|---------------------|------------|----------------------------|--------------|--------------|--------------|
| Release Notification and Corrective Action | | | | | | | | | | | | |
| OPER | | | | | | ATOR Initial Report X Fi | | | | | Final Report | |
| Name of Company OGRID Number | | | | | | Contact | | | | | | |
| Yates Petroleum Corporation 25575 | | | | | | Robert Asher | | | | | | |
| Address | | | | | | Telephone No. | | | | | | |
| 105 S. 4 TH Street | | | | | | 575-748-1471 | | | | | | |
| Facility NameAPI NumberCohiba BPY State #130-015-33999 | | | | | | Facility Type Water Line | | | | | | |
| Cohiba BPY State #1 30-015-33999 | | | | | | | | | | | | |
| Surface Ow | mer | | | Mineral Owner | | | Lease No. | | | | | |
| State State | | | | | | | | | VO-5769 | | | |
| LOCATION OF RELEASE | | | | | | | | | | | | |
| Unit Letter | Section | Township | Range | Feet from the | | South Line | Feet from the | | /est Line | County | | |
| D | 1 | 258 | 27E | 660 | | North | 660 | W N | Vest | Eddy | | |
| L | I | li | | <u> </u> | l | | L | | | | | |
| Latitude_32.16468 Longitude_104.15004 | | | | | | | | | | | | |
| NATURE OF RELEASE Type of Release Volume Recovered | | | | | | | | | | | | |
| Type of Release Produced Water | | | | | | 5 B/PW | | | Volume Recovered 4 B/PW | | | |
| Source of Release | | | | | | Date and Hour of Occurrence | | | Date and Hour of Discovery | | | |
| Poly line Riser | | | | | | 6/8/2011; PM 6/8/2011; PM | | | | | | |
| Was Immediate Notice Given? | | | | | | If YES, To Whom? d Mike Bratcher/NMOCD II | | | | | | |
| Bÿ Whom? | | | | | | Date and Hour | | | | | | |
| Bob Asher/Yates Petroleum Corporation | | | | | | 6/7/2011; PM | | | | | | |
| Was a Watercourse Reached? | | | | | | If YES, Volume Impacting the Watercourse. N/A | | | | | | |
| If a Watercourse was Impacted, Describe Fully.* | | | | | | | | | | | | |
| N/A Describe Cause of Problem and Remedial Action Taken.* | | | | | | | | | | | | |
| | | | | ise in main line pr | ressure | Valves were i | solated from main | n waterli | ne Vacuu | m trucks ca | lled | |
| Describe Area | | | | | 0.5010. | Turres were i | soluted from man | ii waterii | ne. vacau | in ducks ca | <u>neu.</u> | |
| .An approxima | ate area of 6 | 5' X 400' (on p | production | pad and of edge | of pad). | Vertical and | horizontal delinea | ntion sam | ples will | be taken and | d analys | sis ran for |
| TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 | | | | | | | | | | | | |
| will be submitted to the OCD requesting closure. If the analytical results are above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (70', Section 22, T24S-R27E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE | | | | | | | | | | | | |
| RANKING IS 10. Based on enclosed analytical results, impacted soils excavated/hauled, Yates Petroleum Corporation requests closure. | | | | | | | | | | | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger | | | | | | | | | | | | |
| regulations all | operators a | are required to | report and | d/or file certain re e of a C-141 repor | lease no | titications and | d perform correcti | ive action | ns for rele | ases which | may en | danger |
| should their of | perations ha | ive failed to ac | lequately i | investigate and real | mediate | contaminatio | n that nose a threa | at to grou | and water. | surface wa | ter, hur | nan health |
| should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other | | | | | | | | | | | | |
| federal, state, | or local law | s and/or regul | ations. | | | | | | | | | |
| Signature: | | | | | | OIL CONSERVATION DIVISION | | | | | | |
| | | | | | | | | | | | | |
| | | court | | Approved by District Supervisor: | | | | | | | | |
| Printed Name: | Robert Ash | ner | | ANN | | | | | | | | |
| Title: Senior E | nvironment | al Regulatory | A | Approval Date: Z/16/15 Expiration Date: 1/A | | | | | | | | |
| E-mail Address: boba@yatespetroleum.com | | | | | | Conditions of Approval: | | | | | | |
| Date: Wednesday, January 23, 2013 Phone: 575-748-4021 | | | | | | | | | | | | |
| Date. weanest | ay, January | 425, 2015 | rnon | e, 575-748-4021 | 2 | RP-817 | | <u>a</u> | | | | |

* Attach Additional Sheets If Necessary