

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

OCT 02 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

nAB1507736778 **229137**



OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: COG Operating LLC		Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-230-0077	
Facility Name: Myox 28 State #2H		Facility Type: Flowline	
Surface Owner: State		Mineral Owner: State	
		API No. 30-015-39060	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	28	25S	28E	330'	South	330'	West	Eddy

Latitude 32.0942178640043 Longitude -104.099595101218

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: Unknown	Volume Recovered: 0 bbls
Source of Release: Flowline	Date and Hour of Occurrence: 9/19/2014 10:00 am	Date and Hour of Discovery: 9/19/2014 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Robert McNeill	Date and Hour: 9/22/2014 8:00 am (phone call)	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Unknown	
If a Watercourse was Impacted, Describe Fully.* Torrential rains caused flood waters to rise. Waters caused a flowline carrying produced water to break. Wells had been shut in as precaution to the rain. An unknown volume of produced water was washed away in flood waters.		
Describe Cause of Problem and Remedial Action Taken.* The flowline was repaired.		
Describe Area Affected and Cleanup Action Taken.* The impacted area shows no signs of brine impact.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By: 	
Title: Senior Environmental Coordinator	Approved by Environmental Specialist:	
E-mail Address: atrujillo@concho.com	Approval Date: 3/18/15	Expiration Date: N/A
Date: October 2, 2014 Phone: 575-748-6940	Conditions of Approval: FINAL	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-2864

Patterson, Heather, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Thursday, October 02, 2014 3:34 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: (Initial-Final C-141) Myox 28 State #2H (30-015-39060)
Attachments: 09-19-2014 Myox 28 State Com #2H (FL) Initial-Final.pdf

Mr. Bratcher,

COG Operating LLC is reported the release at the **Myox 28 State #2H (30-015-39060)** on 9/22/2014 by phone.

Unit M Section 28 Township 25S Range 28E

The release occurred at 10:00 am on 09/19/2014.

Released: Unknown volume of produced water

Recovered: 0 bbls

This release was caused by torrential rains. Waters caused a flowline to snap. Attached is a C-141 Initial for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

atrujillo@concho.com

2208 W. Main St.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.