District I 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Revised August 8, 2011

Form C-141

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

FAB 1508 236 713 Release Notification and Corrective Action	
NAB 1508 236840	OPERATOR Initial Report Final Report
Name of Company Enterprise Field Services LLC	Contact Dina Babinski
PO Box 4324, Houston, TX 77252	Telephone No. 210-528-3824
Facility Name Pipeline ROW, B-7 Gathering Lateral Facility Type: Gas Gathering Pipeline	
Surface Owner Bureau of Land Management Miner	al Owner NA - Pipeline Lease No. NA
LOCATION OF RELEASE	
Unit Letter Section Township Range Feet from the NENE 14 20S 28E 296	North/South Line Feet from the East/West Line County North 638 West Eddy
Latitude: <u>N 32.580222</u> Longitude: <u>W -104.141698</u>	
NATURE OF RELEASE	
Type of Release Natural Gas, Pipeline Liquids	Volume of Release: 23288 MCF, Volume Recovered: N/A 10 BBL Liquids(estimate)
Source of Release Pipeline Leak and blowdown.	Date and Hour of Occurrence Date and Hour of Discovery 11/09/2014 @ 10:45 MST 11/09/2014 @ 10:45 MST
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Requ	If YES, To Whom?
By Whom? Osman De Leon	Date and Hour 11/09/2014 @ 13:06 MST
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.
☐ Yes ☒ No	NM OIL CONSERVAT
If a Watercourse was Impacted, Describe Fully.* ARTESIA DISTRICT	
	NOV 2 0 2014
Describe Cause of Problem and Remedial Action Taken.*	
Pipeline leak was detected by an Enterprise technician investigating a pressure loss. Pipeline segment was isolated and blown down RECEANIED portion was repaired.	
Describe Area Affected and Cleanup Action Taken.*	
Liquid spill occurred within pipeline ROW with surface staining off ROW. Cleanup activities are currently being performed and additional sampling has been requested to confirm cleanup is satisfactory. All clean-up will be coordinated with landowner.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and	
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability	
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health	
or the environment. In addition, NMOCD acceptance of a C-141 representation federal, state, or local laws and/or regulations.	port does not relieve the operator of responsibility for compliance with any other
rederal, state, or local laws and or regulations.	OIL CONSERVATION DIVISION
	1/
Signature: /w (Tush	Approved by District Supervisor.
Printed Name: Jon E. Fields	Approved by District Supervisor.
Title: Director, Field Environmental	Approval Date: 3 23 15 Expiration Date: NA
E-mail Address: jefields@eprod.com	Conditions of Approval:
Date: 4/204 Phone: 713-381-6684	Remediation per O.C.D. Rules & Guidelines
* Attach Additional Sheets If Necessary	LATER THAN: 4123/15 2RP. 2906

ENTERPRISE PRODUCTS PARTNERS L.P. ENTERPRISE PRODUCTS HOLDINGS LLC (General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

NM OIL CONSERVATION

ARTESIA DISTRICT

NOV 2 0 2014

RECEIVED

7014 1820 0001 6317 7682 Return Receipt Requested

Mr. Mike Bratcher New Mexico Oil Conservation Division District 2 Office 811 South First Street Artesia, New Mexico 88210

RE:

Form C-141 Report for Enterprise Field Services LLC Release on Carlsbad Area Gathering Lines

Dear Mr. Bratcher,

November 14, 2014

Enclosed, please find the required initial C-141 Form report for the unplanned release on our B-7 Line in Eddy County on November 9, 2014.

This report is sent pursuant to NMAC 19.15.29 and as follow-up to verbal notifications made to your office over the phone by Osman De Leon on November 9th, 2014 at 1:06 PM MST. Cleanup activities are currently underway, and a final C-141 form will be submitted when soil sampling results demonstrate that cleanup of the affected area is complete.

If you have any questions or need additional information, please contact Dina Babinski, our area Environmental Supervisor at 210-528-3824, or me at 713-381-6684.

Yours truly,

Jon E. Fields

Director, Field Environmental

/bjm Enclosure