

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

MAR 26 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1508554476 **229137** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: RJ Unit 129	Facility Type: Wellhead

Surface Owner: Federal	Mineral Owner:	API No. 30-015-03780
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	35	17S	29E	1980'	North	1980'	West	Eddy

Latitude 32.7928243621668 Longitude -104.047528594664

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 3 bbls Oil ; 10 bbls PW	Volume Recovered: 0 bbls Oil ; 0 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 3/5/2015 11:00 am	Date and Hour of Discovery: 3/5/2015 11:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A driver from Richard's Energy Compression Services drove over the line causing the line to break. A backhoe was on site and able to isolate the impacted area quickly.

Describe Area Affected and Cleanup Action Taken.*

The impacted area was approximately 10' x 300' in the roadway. The backhoe scraped up the impacted soil and hauled to an NMOCD approved facility. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By  Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 3/26/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date: March 25, 2015 Phone: 575-748-6940	Attached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 4/26/15

2RP-2919

Bratcher, Mike, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Wednesday, March 25, 2015 3:52 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jeff Robertson; James Amos; shughes@blm.gov; Austin Weyant; Lucas Middleton
Subject: (Notification/C-141 Initial) RJ Unit #129 (30-015-03780)
Attachments: 3-5-2015 RJ Unit #129 (FL) Initial.pdf

Mr. Bratcher/Mr. Robertson,

COG Operating LLC is reporting a release on the RJ Unit #129 (30-015-03780)
Unit F Section 35, Township 17S Range 29E
The release occurred at 11:00 am on 3/5/2015
Released: 3 bbls oil ; 10 bbls PW
Recovered: 0 bbls oil ; 0 bbls PW

A driver from Richard's Energy Compression Services drove over the line causing the line to break. A backhoe was on site and able to isolate the impacted area quickly. The impacted area was approximately 10' x 300' in the roadway. The backhoe scraped up the impacted soil and hauled to an NMOCD approved facility. Souder, Miller and Associates is addressing the clean-up of this release on behalf of Concho. Attached is a C-141 (Initial-Final) for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

2208 W. Main St.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that

any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.