

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**FAB 1435830421 Release Notification and Corrective Action**

<b>NAB1510356246</b>		<b>OPERATOR</b>	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company OXY USA WTP LP		Contact CAMPBELL, RODNEY		
Address 329 Marathon Rd, Lakewood		Telephone No. (575) 628-4167		
Facility Name INDIAN BASIN GAS PLANT		Facility Type GAS PROCESSING FACILITY		

Surface Owner	Mineral Owner INDIAN BASIN	Lease No.
---------------	----------------------------	-----------


**LOCATION OF RELEASE**

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

**32.4645839** **104.5744466**  
Latitude 32°27'52.502" Longitude 104°34'28.004"

**NATURE OF RELEASE**

Type of Release Gas	Volume of Release 393.6 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 2/1/2014 3:45:00 PM	Date and Hour of Discovery 2/1/2014 3:45:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		



Describe Cause of Problem and Remedial Action Taken.\*  
Cause:  
OXY INDIAN BASIN GAS PLANT FLARES RESIDUE SALES GAS FOR 10 MINUTES DUE TO HIGH OXYGEN CONTENT. DUE TO SHORT DURATION, THE SOURCE OF OXYGEN COULDN'T BE DETERMINED. THERE WERE TWO DIFFERENT EVENTS ON THE SAME DAY. THE FIRST EVENT OCCURRED AT 1545-1548. SECOND EVENT OCCURRED AT 1821-1828.  
Remedial Action Taken:  
OPERATIONS DIDN'T HAVE TIME TO CHECK METERS WITH PORTABLE OXYGEN ANALIZER DUE TO SHORT DURATIONS. OPERATIONS SAMPLED THE STABILIZER DISCHARGE METER FOR THE SECOND EVENT, BUT DIDN'T SHOW ANY SIGN OF OXYGEN. OPERATIONS NOTIFIED FIELD PRODUCTION COORDINATOR AND FIELD MEASUREMENT TECH.

Describe Area Affected and Cleanup Action Taken.\*  
N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: RODNEY CAMPBELL		Approved by District Supervisor:	
Title: <b>HES Specialist</b>	Approval Date: <b>4/13/15</b>	Expiration Date: <b>N/A</b>	
E-mail Address: RODNEY_CAMPBELL@OXY.COM	Conditions of Approval: <b>FINAL</b>		Attached <input type="checkbox"/>
Date: <b>2-10-14</b>	Phone: (575) 628-4167		

**2RP-2945**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company OXY USA WTP LP	Contact CAMPBELL, RODNEY	
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4167	
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING FACILITY	
Surface Owner	Mineral Owner INDIAN BASIN	Lease No.


#### LOCATION OF RELEASE

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

#### NATURE OF RELEASE

Type of Release Gas	Volume of Release 393.6 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 2/1/2014 3:45:00 PM	Date and Hour of Discovery 2/1/2014 3:45:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Cause: OXY INDIAN BASIN GAS PLANT FLARES RESIDUE SALES GAS FOR 10 MINUTES DUE TO HIGH OXYGEN CONTENT. DUE TO SHORT DURATION, THE SOURCE OF OXYGEN COULDN'T BE DETERMINED. THERE WERE TWO DIFFERENT EVENTS ON THE SAME DAY. THE FIRST EVENT OCCURRED AT 1545-1548. SECOND EVENT OCCURRED AT 1821-1828. Remedial Action Taken: OPERATIONS DIDN'T HAVE TIME TO CHECK METERS WITH PORTABLE OXYGEN ANALIZER DUE TO SHORT DURATIONS. OPERATIONS SAMPLED THE STABILIZER DISCHARGE METER FOR THE SECOND EVENT, BUT DIDN'T SHOW ANY SIGN OF OXYGEN. OPERATIONS NOTIFIED FIELD PRODUCTION COORDINATOR AND FIELD MEASUREMENT TECH.		
Describe Area Affected and Cleanup Action Taken.* N/A		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: RODNEY CAMPBELL		Approved by District Supervisor:	
Title: <u>HEs Specialist</u>		Approval Date:	Expiration Date:
E-mail Address: RODNEY_CAMPBELL@OXY.COM		Conditions of Approval:	
Date: <u>2-10-14</u> Phone: (575) 628-4167		Attached <input type="checkbox"/>	

Copy