

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company	COG Operating LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Choctaw 3" Water Line	Facility Type	3" Water Line

Surface Owner	State	Mineral Owner		Lease No.	(API# 30-015-36351)
				Closest well location	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	16	17S	31E					Eddy

Latitude N 32 49.742 Longitude W 103 52.417

**NATURE OF RELEASE**

Type of Release	Produced water / Skim oil	Volume of Release	80 bbls	Volume Recovered	75 bbls
Source of Release	3" poly water line	Date and Hour of Occurrence	06/29/2012	Date and Hour of Discovery	06/29/2012 @ 7:00 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- OCD		
By Whom?	Michelle Mullins	Date and Hour	06/30/2012 @ 6:50 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

A new 3" poly water line was accidentally left un-fused to the existing water line while replacing poly that had been burned by a fire earlier in the month. The un-fused poly line released fluid onto the previously burned area in the pasture north of the Yucca/Willow Tank Battery. We have fused the poly lines together and returned to service.

Describe Area Affected and Cleanup Action Taken.\*

Initially 80 bbls were released from the 3" poly line and we were able to recover 75 bbls with a vacuum truck. The release occurred north of the Yucca/Willow Tank Battery in the pasture measuring approximately 3' x 100". All free fluid has been recovered. BBC International completed remediation of the facility in accordance with the remediation plan approved by NMOCD on 11/16/2012 via email from Mike Bratcher.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Josh Russo		Approved by District Supervisor: 	
Title: HSE Coordinator		Approval Date: 4/12/15	Expiration Date:
E-mail Address: jrusso@conchoresources.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 04/04/2013 Phone: 432-212-2399			

\* Attach Additional Sheets If Necessary

2 RP 1220  
Final