

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report



Name of Company COG Operating LLC	Contact Pat Ellis	
Address 550 W. Texas, Suite 1300 Midland, Texas 79701	Telephone No. (432) 685-4332	
Facility Name Antelope State Tank Battery	Facility Type Tank Battery	
Surface Owner: State	Mineral Owner	Lease No. (API#) 30-015-32040

LOCATION OF RELEASE

Unit Letter K	Section 36	Township 17S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	--------

Latitude N 32.78841° Longitude W 103.82626°

NATURE OF RELEASE

Type of Release: Produced Fluid	Volume of Release 23 bbls	Volume Recovered 21 bbls
Source of Release: Equalizer	Date and Hour of Occurrence 4/16/2011	Date and Hour of Discovery 4/16/2011 8:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Josh Russo	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The water transfer pump malfunctioned; it has since been repaired and put back into service.		
Describe Area Affected and Cleanup Action Taken.* Tetra Tech inspected site and collected samples to define the spills extent. Based on the assessment, COG will perform some general house keeping in the area of AH-2 to remove the surface chloride impacted soil. Tetra Tech prepared closure report and submitted to NMOCD for review and approval.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez <i>Ike Tavarez COG</i>	Approved by District Supervisor: 	
Title: Project Manager	Approval Date: <i>4/22/15</i>	Expiration Date:
E-mail Address: Ike.Tavarez@TetraTech.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>8-31-11</i>	Phone: (432) 682-4559	

* Attach Additional Sheets If Necessary

2 RP 761
Final