

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company – <b>Devon Energy</b>	Contact – <b>Roy White, Foreman</b>
Address – <b>6488 Seven Rivers Hwy – PO Box 250</b>	Telephone No. – <b>575-513-1741</b>
Facility Name – <b>Parkway # 21</b>	Facility Type

Surface Owner	Mineral Owner	Lease No. API # 30-015-32686 2RP-706
---------------	---------------	--------------------------------------


**LOCATION OF RELEASE**

Unit Letter P	Section 28	Township 19S	Range 29E	Feet from the 330'	North/South Line South	Feet from the 400'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.62534 Longitude -104.07259

**NATURE OF RELEASE**

Type of Release – <b>Oil</b>	Volume of Release <b>152 bbls</b>	Volume Recovered <b>23 bbls</b>
Source of Release – Load line valve in front of tank broke	Date and Hour of Occurrence <b>1/23/11 – 10:30 am</b>	Date and Hour of Discovery <b>1/23/11 – 10:30 am</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Darold Gray – OCD</b>	
By Whom? – <b>Roy White, Foreman</b>	Date and Hour <b>1/23/11 – 11:55 am</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Load line valve in front of tank froze and broke in two. Tanks were cleaned, bottoms recoated and all valves replaced. A vacuum truck was used to recover 23 bbls of oil. Removed impacted soil from release area.

Describe Area Affected and Cleanup Action Taken.\*

Impacted area 10'x100' in front of tanks. Impacted area was excavated to the depth of 1 foot; contaminated soil transported to a NMOCD approved facility for disposal. The area was backfilled to grade using new material transported from local borrow pit.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>David Adkins, TALON/LPE</b>	Approved by District Supervisor:	
Title: <b>Agent/Devon Energy</b>	Approval Date: <b>4/22/15</b>	Expiration Date:
E-mail Address: <b>dadkins@talonlpe.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>6/23/11</b>	Phone: <b>575-746-8768</b>	

\* Attach Additional Sheets If Necessary

2RP 706  
Final